

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2020

Submitted Date:

09/04/2020

Document Number:

694500223

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 _____ NEIDEL, KRIS _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 16690

Name of Operator: CHEVRON PIPELINE COMPANY

Address: 2750 COUNTY ROAD 102

City: RANGELY State: CO Zip: 81648

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|--------------|--------------------------|---------|
| Fischer, Alex | | alex.fischer@state.co.us | |
| Eggert, Derek | 281-753-0816 | dhyg@chevron.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------------------|--------|-------------|------------|---------|---------------------|-------------|
| 449632 | SPILL OR RELEASE | CL | 09/18/2017 | | - | SPILL/RELEASE POINT | EI |

General Comment:

On 8/26/2020 COGCC Staff, Kris Neidel inspected the Rangely C-4 spill path. Spill 449632 and Remediation #10149. Weather was partly cloudy, hot and 92 degrees. The area referred to as the bowl is near the source of the spill, oil had more time to soak into the ground in this area. Initial Spill response removed heavily contaminated leaving a larger depression in the ground. Soil in the bowl has been undergoing in situ treatment (water, amendment and tilling). Chevron staff was on location to collect soil samples at 1 foot BGS (below ground surface) and 2 feet BGS in four location around the perimeter of the bowl. The north west and the north east bowl samples had detectable hydrocarbon odor. Samples were also collected at 6 locations in the flow path, just down grade from the bowl. These samples were collected at 1 foot BGS and 2 foot BGS. None of these samples had detectable odor. Samples were collected from other areas described in the remediation project documents, in division 3. No detectable odor was present in division 3 samples. General comments on the spill path: Areas of the spill path that have been granted 'no further action' have vegetation. Chevron Pipeline has been working with the BLM on revegetation and reclamation in these areas. Areas that have remaining impact have continued to be tilled, the surface is soft from tilling and free of vegetation (also believed to be from tilling). The entire spill path is free of any visible hydrocarbon. See attached Photos.

Environmental**Spill/Remediation:**Comment: [Remediation project is ongoing.](#)Corrective Action: [Submit sample results, on a Form 27, within 30 days of receiving results.](#)

Date: 10/09/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------|---|
| 402482858 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5239718 |
| 694500224 | photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5239717 |