

# LEASE INSPECTION FORM

\_\_\_ NEW WELL

Well Name: McCallum Unit W-6  
 Operator: Asamera  
 Location: NWNW 18 9N 78W  
 Field: McCallum

API #: 05- 057 - ~~5330~~ 05057  
 Permit #: \_\_\_\_\_  
 County: JACKSON  
 Inspector: Larry Robbins

Well Status: ☐ PR ☒ SI ☐ TA ☐ AC\* \*Forward to UIC

Date of Inspection: 10.8.91



CAPABLE OF PRODUCTION GIVEN EXISTING SURFACE EQUIPMENT: ☐ Y ☒ N

CHANGE IN WELL OR EQUIPMENT STATUS SINCE LAST INSPECTION: ☐ Y ☒ N

LEASE #: \_\_\_\_\_ MULTIPLE WELL LEASE: ☐ Y ☒ N MULTIPLE WELL T-B: ☐ Y ☒ N

API: 05-	-	LEGAL:	WELL #:	STATUS:
API: 05-	-	LEGAL:	WELL #:	STATUS:
API: 05-	-	LEGAL:	WELL #:	STATUS:
API: 05-	-	LEGAL:	WELL #:	STATUS:

LEASE SIGN: ☐ Y ☒ N \* TANK ID: ☐ Y ☒ N ☒ NA \* TANK BERM: ☐ Y ☒ N ☒ NA \*

BRADENHEAD PRESSURE: \_\_\_\_\_ FLUID: ☐ Y ☒ N TYPE: \_\_\_\_\_  
 TUBING PRESSURE: \_\_\_\_\_ TUBING-CASING PRESSURE: \_\_\_\_\_  
 LIFT SYSTEM: NA \_\_\_\_\_ FLOWING \_\_\_\_\_ PUMP JACK \_\_\_\_\_ GAS LIFT \_\_\_\_\_ DOWNHOLE PUMP \_\_\_\_\_ OTHER \_\_\_\_\_

PRODUCTION EQUIPMENT: STORAGE TANKS \_\_\_\_\_ BBLS \_\_\_\_\_ BBLS VERT H-T \_\_\_\_\_ HORIZ H-T \_\_\_\_\_  
 SEP \_\_\_\_\_ GMR \_\_\_\_\_ OTHER No production equipment on location

PRODUCTION EQUIPMENT LOCATION: \_\_\_\_\_

OBSERVED METHOD OF WATER DISPOSAL: EVAP PIT \_\_\_\_\_ INJECTED\* \_\_\_\_\_ TANKS/TRUCKED \_\_\_\_\_ UNKNOWN \_\_\_\_\_ NA \_\_\_\_\_

WELL CLASS 3- \_\_\_\_\_ WATER PROD: ESTIMATED \_\_\_\_\_ REPORTED \_\_\_\_\_ TDS \_\_\_\_\_

\*INJECTION FACILITY NAME: \_\_\_\_\_ LOCATION: \_\_\_\_\_

COMMENTS: \_\_\_\_\_

DISPOSAL PITS: ☐ Y ☒ N PERMITTED: ☐ Y ☒ N \* OIL ON PIT FLUID: ☐ Y ☒ N ☒ NA \*  
 COVERED: ☐ Y ☒ N LINED: ☐ Y ☒ N LINER REQUIRED: ☐ Y ☒ N ☒ NA \*

DIMENSIONS: \_\_\_\_\_

LOCATION: \_\_\_\_\_

COMMENTS: \_\_\_\_\_

SKIM TANK/PIT: ☐ Y ☒ N TYPE: EARTH \_\_\_\_\_ CONCRETE \_\_\_\_\_ METAL \_\_\_\_\_ WOOD \_\_\_\_\_

COVERED: ☐ Y ☒ N OIL ON PIT FLUID: ☐ Y ☒ N ☒ NA \*

DIMENSIONS: \_\_\_\_\_

LOCATION: \_\_\_\_\_

COMMENTS: \_\_\_\_\_

COMMENTS: well is shut-in. GAS is visible leaking out of valve and disconnected coupling. Around the valve leak it's frosted probably a result of leaking CO2 around valve stem packing.

RECOMMENDED ACTION: \_\_\_\_\_

\*VIOLATIONS: ☐ Y ☒ N

NOTICE SENT: ☐ Y ☒ N

DATE: 10.8.91