

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/16/2020

Submitted Date:

11/17/2020

Document Number:

690102161

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Maclaren, Joe 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		cogcc@kpk.com	
Knop, Max		mknop@kpk.com	
Canfield, Chris		chris.canfield@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478542	SPILL OR RELEASE	AC	11/12/2020		-	Cosslet A 9 Flowline	EG

General Comment:

Engineering Integrity inspection performed on November 16th, 2020 in response to initial form 19 spill report Doc #402530467 received by COGCC on 11/11/2020 that outlines: Third-party notified KPK about an observed flowline release detected from an aerial leak inspection survey. KPK immediately shut-in associated flowline to stop the release. Only soil impacted at the surface could be removed due to other buried production lines in the area. Excavation activities at the release location will need to be performed with hydrovac operations and a third-party stand-by.

Corrective Actions identified during this field inspection are outlined in the flowline section of report. Photos uploaded.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Flow Line

#

Comment: COGCC Inspector spoke with KPK field personnel on site. A failure was identified on the off location flowline (OLF) at 40.075907, -104.966630. The failure occurred on the 3" fiberglass OLF where it crosses a pipeline ROW; pipelines were recently constructed in the area (Western Midstream). Soils movement in the ROW appear to have resulted in the development of a crack in the fiberglass OLF. The KPK field crew is in the process of completing flowline repairs; approximately 100 linear feet of 3" fiberglass flowline has been cut out and replaced with 3"HDPE SDR 11 (poly) flowline. Connections at each end have been made using fiberglass/ poly fitting transitions. Excavation and remediation work is in process.

Corrective Action: Update CA section of supplemental form 19 spill report to include the following:
 1) Root cause of flowline failure(s) resulting in this release
 2) Measures taken to prevent a recurrence
 3) Written description of all flowline repair, replacements completed
 4) Perform flowline pressure testing and verify integrity of repairs/ reconnections completed prior to return to service (rule 1102.j.4 and 1102.O). Upload pressure testing chart to COGCC Form 19 subsequent.

Date: 12/18/2020

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 478542 Type: SPILL OR API Number: - Status: AC Insp. Status: EG**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402534753	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5292931
690102162	Excavation; OLF exposed (view NW)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5292928
690102163	3" fiberglass to 3" HDPE SDR 11 transition	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5292929
690102164	OLF repair; Midstream pipeline exposed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5292930