

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/08/2020

Submitted Date:

12/11/2020

Document Number:

696202122**FIELD INSPECTION FORM**Loc ID 335889 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Arthur, Denise		denise.arthur@state.co.us	
, Laramie		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335889	LOCATION	AC			-	Cascade Creek 697-09-61	RI

General Comment:

On 12/08/2020, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at Laramie Energy's Cascade Creek 697-09-61 location in Garfield County, Colorado.

This inspection is a follow up to FIR #696201787 and #696201980 to document compliance with the following corrective actions: 1002.f.(2): Stormwater

This inspection is also a follow up to Resolution doc. #402527730 stating corrective actions have been completed.

It was observed in this inspection that the Location remains out of compliance with Rule 1002.f and corrective actions.

Refer to the "Stormwater" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Previous inspections observed that BMPs were missing, or insufficient to stabilize the cut slopes on the north and western areas of the location, and required Operator to comply with 1002.f rules. Operator submitted FIRR No. 402527730 stating CAs have been addressed.

It was observed in this inspection that Operator implemented mulch on the cutslope of the northwest corner of the Location behind the tank battery; BMP has not been installed in accordance with good engineering practices or maintained in proper functioning condition. BMPs not installed to stabilize/protect the remaining cut slopes on the north ends of the Location as identified in the previous inspections.

BMPs remain insufficient to stabilize and protect the cut slopes.

Corrective Action: Corrective action has not been addressed in its entirety and remains applicable: Install or repair required BMPs per Rule 1002.f.(2)C.

Date: 10/02/2020

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696202123	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5308645