

Inspection Photos

API: 043-06221

Operator: AUSCO PETROLEUM INC

Inspection Date: 4/22/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 4/22/2021

Inspection Photos



Photo 1. Facing southwest along the access road. Stormwater from the road is creating erosion in area shown at red arrow.. The wattles placed in this area are displaced and are not controlling erosion. Previous corrective action has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 4/22/2021

Inspection Photos



Photo 2. There is erosion along the access road. Stormwater is diverted down the road and into drainage area shown in previous photo. The erosion needs to be repaired and stormwater needs to be properly diverted. Previous corrective action has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 4/22/2021

Inspection Photos



Photo 3. Facing south toward the location. The fence around the vegetated area is not maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 4/22/2021

Inspection Photos



Photo 4. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 4/22/2021

Inspection Photos



Photo 5. There are wattles displaced at the southwest side of the location. Wattles need to be repaired and maintained. Previous corrective action has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 4/22/2021

Inspection Photos



Photo 6. There is an erosion channel at the southwest side of the location. Stormwater is directed to this area from the top perimeter ditch. BMP's are needed in this area to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 4/22/2021

Inspection Photos



Photo 7. There is an erosion occurring off the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 4/22/2021

Inspection Photos



Photo 8. There is oil leaking from the pumpjack engine. Stained soil have not been cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 4/22/2021

Inspection Photos



Photo 9. There is stained soil at the outlet of the PW tank.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 4/22/2021

Inspection Photos



Photo 10. The top perimeter ditch is directing stormwater toward the road which has deposited sediment onto the road. BMP's are needed in this area. Previous corrective action has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 4/22/2021

Inspection Photos



Photo 11. There is erosion occurring across the road at the north side of the location caused by stormwater directed from the top perimeter ditch shown in the previous photo. Previous corrective action has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06221 | Date: 4/22/2021