

Inspection Photos

Operator: Hilcorp Operating
API: 067-08517
Date: 4/22/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation appears to be progressing with sand dropseed, Indian ricegrass, western wheatgrass, and rubber rabbitbrush.



Photo 3. View of rock velocity checks along the access road that are full of sediment and are not adequate BMPs for this slope.



Photo 4. View of wattles at the top of the eastern cut-slope that need maintenance. Erosion controls (ie jute mat, straw blanket, etc. are needed to stabilize blare soils on the cut-slope. Care needs to be take to prevent damage to desirable perennial vegetation.



Photo 5. View of wattle in the southeastern project area, that is full of sediment and needs maintenance.



Photo 6. View of reference area comprised of pinyon and juniper woodland with sagebrush shrubland, blue grama, Indian ricegrass, and mat penstemon.