

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/12/2021

Submitted Date:

05/14/2021

Document Number:

691201497

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Graber, Candice (Nikki) 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 4680

Name of Operator: DCP OPERATING COMPANY LP

Address: 370 17TH STREET - SUITE 2500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Steve Weathers		SWWeathers@dcpmidstream.com	
Axelson, John		john.axelson@state.co.us	
Hayes, Branden		bshayes@dcpmidstream.com	
Jeb Watts		jwatts@tasman-geo.com	
Kristin Pekot		kristin.pekot@state.co.us	

General Comment:

This is an environmental inspection in response to a spill reported by Operator on 5/12/2021; release occurred on the evening of 5/11/2021. Release has been stopped and was not ongoing.

DCP and Tasman personnel met with COGCC inspector and provided details of release and cleanup efforts. Release was caused by equipment failure at an above ground storage condensate tank (Photo 1). Operator reports that the release was stopped and cleanup efforts were initiated immediately upon discovery. Vacuum trucks were on location within an hour of release discovery and cleanup was ongoing at the time of the inspection.

Due to heavy rainfall during the release condensate mixed with rainwater spread across the location approximately 375' east and 150' south to the edge of the facility's perimeter spill control berm (Photos 2-6). At the eastern terminus of the spill, condensate mixed rainwater migrated below the berm and off location impacting adjacent surface water (Evans Town Ditch) (Photos 8-12). Booms were deployed in the ditch at the release point (multiple), immediately downstream from the release point (2) and approximately 600' downstream (2) (Photos 13-16).

Any corrective actions from previous inspections that have not been addressed are still applicable. Inspection of spill area only, photos attached to document site conditions.

Environmental**Spills/Releases:**

Type of Spill: CONDENSATE

Estimated Spill Volume: _____

Comment: At the time of inspection crews were continuing to delineate the extent of impacts. Soil and surface water samples had been collected and submitted for laboratory analysis.

Corrective Action: Initial Form 19 Document #402687618 has been approved. Spill cleanup shall be documented under Spill/Release ID#479990, the next report is due by 5/21/2021.

Date: 05/21/2021

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691201498	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429272