

WORKOVER PROCEDURE		Verdad Resources
Lauck #1 SHL: 40.111169°N/-104.477900°E; SWNE S30 T2NR63W 6PM		
Weld County, CO API: 05-123-05052 Date: 5/18/2021 AFE: TBD		
WELL DATA Re-Enter P&A		
GL Elev: 4,844' Spud Date: 03/23/1955		TD: 7,387' KB PBTD: Surface TD is @7,387'
CASING		
Surface: 10-3/4", 32#, J-55, @174'. Cemented w/ 125 sxs, Cement from 174' to sfc Hole Size: Not Known to 174' (Assumed 13-3/4") Production: No Casing Hole Size: Not Known to 7,387' (Assumed 7-7/8" bore) Directions to Location: From Keenesburg, CO (I-76 and Exit 39), turn South on Market St and continue for 0.3mi. Turn left and head west on Woodward Ave for 0.6mi and follow onto WCR 16-1/2 for 1.6mi. Lease road will be on the North side of the county road.		
Formation Tops: Base of Fox Hills 762'; Top of the Niobrara 6678' (est)		
PROCEDURE		
<ol style="list-style-type: none"> 1. Provide 48 hr notice Form 42 to COGCC prior to rig up per Form 6 COA 2. Contact landowner 48 hours prior to commencing work 3. Build temporary pad and access road for completion rig and cement unit 4. Verify well location and excavate well. 5. Verify casing size, cut off cap, weld on slip collar w/ wellhead, set cellar ring and back-fill. 6. MIRU WO Rig, beam, doghouse, BOP, accumulator, rig pump, shaker tank, rig tank, 9.5ppg water-based mud, pipe racks, 3-1/8" collars, 2-7/8" work string, power swivel, freshwater tanks. 7. Make up BHA ; 2 7/8 EUE string, 2x 3-1/8" drill collars, Float, POBS, 7-7/8" roller-cone bit. 8. RIH and drill out surface casing plugs. Circulate 2 bottoms up. 9. Wash/Ream to tag plug @ 7312'. If plug not found or is below 7275', call engineer. May require additional plug to isolate J- Sand. 10. Circulate and condition hole. 11. TOOH Laydown BHA. 12. TIH with open ended tubing and notched collar or undersized mill. Rig up cement crew. 13. Pump 15.8# 130 sks Class G neat balanced plug from 6,778' to 6,478'. Verify Cement Volume calculation with cement company 14. POOH to 5500' circulate for 4 hours or cement company recommended time 15. RIH and tag cement plug. Note depth/time tagged. If plug not tagged, contact Engineer. 16. TOOH to 2,500', pump 15.8# 45 sks Class G Neat from 2,500' to 2,400'. 17. POOH to 1500' circulate for 4 hours or cement company recommended time 18. RIH and tag cement plug. Note depth/time tagged. If plug not tagged, contact Engineer. 19. TOOH to 850', pump 15.8# 90 sks Class G Neat from 850'-650'. 20. POOH to surface and wait on cement 21. RIH and tag cement plug. Note depth/time tagged. If plug not tagged, contact Engineer. 22. TOOH to 225', pump 15.8# 130 sks Class G Neat from 225' to surface. POOH and LD tbg, top off cement as needed. 23. RDMO Cementers, Rig, and supporting equipment. Tidy location and prep for reclamation. 24. After 5 days, verify TOC is within 5' of surface. Top off if needed. Excavate cellar ring and wellhead, cut off casing 6' below ground level and weld on cap with full legal description welded onto plate. Back fill hole. 25. Reclaim location. 26. Submit Form 6 Subsequent and Form 42 for completion of COA. 		