

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/27/2021

Submitted Date:

07/27/2021

Document Number:

689501304**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: Brown, Kari On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
,		mknop@kpk.com	
Canfield, Chris		chris.canfield@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480275	SPILL OR RELEASE	AC	07/09/2021		-	E. Stieber Consolidation	EI

**General Comment:**

Environmental inspection of E. Stieber Consolidation Spill (COGCC ID 480275(AC)/Complaint Doc #200449776) conducted 7/27/21. Inspections previously submitted under API 05-123-10115. At the time of inspections crews were on site backfilling clean imported soils into impacted groundwater and free product.

[Photos attached to document site conditions.](#)



**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Spill excavation is open and actively being backfilled (approx 10'x20'x8'). Impacted groundwater and free product were observed in the excavation and soil impacts remained in-situ (Photo 4). Excavator operator indicated that they were backfilling temporarily to allow for crews to repair the damaged pipeline and return it to service.

Corrective Action: Immediately remove pooled product from excavation in accordance with Rule 912.a.(2). In accordance with Rule 912.a.(6) No later than 90 days after a Spill or Release is discovered Operator will submit a Form 19 Supplemental requesting closure pursuant to Rule 913.h and supported by adequate documentation to demonstrate closure or a Form 27 Workplan with a timeline for investigation and closure of this release. If Remediation will continue under an approved Form 27, also submit a Form 19 ±Supplemental requesting closure of this spill referencing the approved Remediation workplan (10/4/21). Operator will provide notice to COGCC EPS Kari Brown (kari.l.brown@state.co.us) at least 48 hours prior to backfill or any sampling events performed on location. Note that samples collected must be analyzed for Table 915-1 parameters. On the next Form 19 subsequent operator is to provide the root cause of the incident and preventative measures that will be taken to prevent reoccurrence on this and other flowlines at this location. Please give the location of the failure (i.e. 6 O'clock position) and if the root cause is corrosion explain if it is external or internal. Please also list the wells associated with this facility on the form 19 subsequent.

Date: 10/04/2021

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Waste Management:**

Type \_\_\_\_\_ Management \_\_\_\_\_ Condition \_\_\_\_\_ GPS (Lat) (Long) \_\_\_\_\_

Oily Soil	Other	Inadequate			
Comment	Pooled product was noted in the excavation on 7/9, 7/12, 7/20, and 7/27 and soil impacts remained visible in-situ on all sidewalls on 7/27.				
Corrective Action	Immediately remove pooled product from excavation in accordance with Rule 912.a.(2).				Date: 07/16/2021

**Spill/Remediation:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402761674	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5490493">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5490493</a>
689501305	Field Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5490492">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5490492</a>