

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/06/2021

Submitted Date:

10/06/2021

Document Number:

700703325

FIELD INSPECTION FORM

Loc ID 335640 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Operator Information:
OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
13 Number of Comments
5 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Thomson, Bud		BLThomps@BLM.gov	
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278632	WELL	PR	05/01/2021	GW	103-10609	FEDERAL RGU 44-1-298	PR
290889	WELL	PR	06/04/2007	GW	103-11027	FEDERAL RGU 343-1-298	PR
290890	WELL	PR	06/04/2007	GW	103-11026	FEDERAL RGU 32-1-298	PR
290891	WELL	PR	05/01/2021	GW	103-11025	FEDERAL RGU 43-1-298	PR

General Comment:

COGCC Inspection Report Summary
On Tuesday 10/5/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RGU 44-1, at Location # 335640 in Rio Blanco county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.

During this inspection the following compliance issues were observed:

1. Cut slope is lacking stabilization and has signs of erosion, access road also shows signs of erosion.
2. Lack of battery signage.
3. Well signs are becoming illegible.
4. One tank heater is open for wildlife to enter.
5. Three quad unit horizontal separators includes 6 glycol storage tanks, approximately 174" x 33" x 42" = 25 BBLs each, storage vessels contain no labeling to specify capacity or chemical hazard information.

Refer to photograph of observed compliance issue.
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:	See stormwater		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Comply with rule 605.e		Date: 01/07/2022
Type	WELLHEAD		
Comment:	Well signs are becoming illegible and faded.		
Corrective Action:	Install sign to comply with Rule 605.g.		Date: 01/07/2022
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Three quad unit horizontal separators includes 6 glycol storage tanks, approximately 174" x 33" x 42" = 25 BBLS each, storage vessels contain no labeling to specify capacity or chemical hazard information.		
Corrective Action:	Install proper labeling		Date: 01/07/2022

Emergency Contact Number:		
Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	One tank heater is open for wildlife to enter.		
Corrective Action:	Eliminate possibility of wildlife to enter		Date: 10/15/2021

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Bird Protectors	# 5		
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank in plastic containment		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		
Corrective Action:		Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>278632</u>	Type:	<u>WELL</u>	API Number:	<u>103-10609</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>290889</u>	Type:	<u>WELL</u>	API Number:	<u>103-11027</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>290890</u>	Type:	<u>WELL</u>	API Number:	<u>103-11026</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>290891</u>	Type:	<u>WELL</u>	API Number:	<u>103-11025</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						

Comment: 1. Cut slope is lacking stabilization and has signs of erosion, access road also shows signs of erosion.

Corrective Action: Install or repair required BMPs

Date: 01/07/2022

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703329	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5549017