

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402847843

Date Received:
10/20/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Gee, Greg</u>	<u>903-987-0353</u>	<u>ggee@ogrisop.com</u>
		<u>efitzgerald@ogrisop.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690201750
Inspection Date: 07/07/2021 FIR Submit Date: 07/08/2021 FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 307299

Location Name: APACHE CANYON-634S67W Number: 20SWNW County: LAS ANIMAS
Qtrqtr: SWN Sec: 20 Twp: 34S Range: 67W Meridian: 6
Latitude: 37.069810 Longitude: -104.919870

FACILITY - API Number: 05-071- -00 Facility ID: 217414

Facility Name: APACHE CANYON Number: 20-5
Qtrqtr: SWN Sec: 20 Twp: 34S Range: 67W Meridian: 6
Latitude: 37.069810 Longitude: -104.919870

CORRECTIVE ACTIONS:

1 CA# 152509

Corrective Action: Cover and protect the area around the wellhead to prevent entry. Date: 03/12/2021
Response: CA COMPLETED Date of Completion: 10/11/2021

THE METAL GRATE UNDER THE WELL HEAD WAS RECONFIGURED TO PREVENT ENTRY.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 152510

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 07/12/2021

Response: CA COMPLETED

Date of Completion: 10/11/2021

Operator
Comment:

THE SEDIMENT WAS REMOVED FROM THE CATTLE GUARD. SOME OF THE CULVERT OUTLETS ALONG THE MAIN SOUTH FORK LEASE ROAD WERE BELOW GRADE AND WOULD NOT DRAIN PROPERLY. DRAINAGE WAS ESTABLISHED FOR THE OUTLETS. THE CULVERTS WERE CLEANED OUT WITH THE HYDRO-VAC EQUIPMENT AND THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE CULVERT INLETS. THE ROAD SURFACE WAS CROWNED TO CREATE SHEET FLOW AND ELIMINATE THE TIRE RUTS. ADDITIONAL ROAD BASE/GRAVEL WAS INSTALLED TO THE ROADWAY SURFACE TO PROVIDE ADDED STABILIZATION. THE ACCESS ROAD INTO LOCATION HAD ARMOR INSTALLED IN THE SPILL WAY TO PREVENT SCOURING OF THE FILL SLOPE. THERE IS A BEAVER DAM UP RIVER WHICH IS CAUSING THE STREAM TO BACK-UP AND RISE IN THIS AREA. SPOKE WITH CPW REGARDING THIS ISSUE. ADDITIONAL GRAVEL WAS ADDED TO THE ACCESS ROAD AND THE AREA SOUTHWEST OF PAD FOR DRIP TRUCK ACCESS.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed:

Title: Sr. Environmental Tech.

Date: 10/20/2021 2:11:58 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402847908	PHOTO LOG
-----------	-----------

Total Attach: 1 Files