

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/30/2021

Submitted Date:

12/01/2021

Document Number:

693903914

FIELD INSPECTION FORM

Loc ID 443658	Inspector Name: ROY, CATHERINE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 10749 Name of Operator: SIMCOE LLC Address: 1199 MAIN AVE SUITE 101 City: DURANGO State: CO Zip: 81301				Findings: 4 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443655	WELL	PR	03/28/2016	GW	067-09956	Ford H 1	RI
443657	WELL	PR	03/28/2016	GW	067-09958	Ford H 3	RI

General Comment:

On 11/30/2021 Catherine Roy conducted a reclamation and stormwater inspection. During this inspection the following compliance issues were observed:

-Stormwater controls need to be installed to stabilize erosion along the access road and within the southeastern corner of the project area. This includes properly diverting stormwater flows, installation of BMPs, and stabilization of culvert inlets and outlets. All stormwater controls need to be selected, sized, installed, and maintained according to good engineering practices. Current practices and materials are not adequate. Corrective action date: 12/30/2021.

-Remove gravel and rock deposits from the intermittent stream and discharged areas down-slope of the access road. Stream is an intermittent stream and rock is considered a discharge into Waters of the State. Any damage to vegetation during gravel/rock removal process will require further seeding and reclamation. Corrective action date: 12/30/2021

-Access road is shared with Logos Operating, it is the responsibility of both operators to ensure compliance on shared road. See below, and attached photos for additional detail.

Inspected Facilities									
Facility ID:	443655	Type:	WELL	API Number:	067-09956	Status:	PR	Insp. Status:	RI
Facility ID:	443657	Type:	WELL	API Number:	067-09958	Status:	PR	Insp. Status:	RI

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND, TIMBER

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? **Fail** _____

Comment

Significant volumes (see photos for volume est.) of gravel and rock debris observed down-slope from the access road and deposited approximately 50ft downstream from road crossing, within the intermittent streambed (Waters of the State).

Corrective Action

-Remove gravel and rock deposits from the intermittent stream and discharged areas down-slope of the access road. Stream is an intermittent stream and rock is considered a discharge into Waters of the State. Any damage to vegetation during gravel/rock removal process will require further seeding and reclamation. Corrective action date: 12/30/2021

Date **12/30/2021**Unused or unneeded equipment onsite? **Pass** _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND, TIMBER _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: Stormwater erosion was observed along the access road where stormwater flows are not properly diverted and de-energized, culverts not properly stabilized, and BMPs are not in place. Wattles in the southeastern well pad are out of place and an erosional channel is forming.</p> <p>Corrective Action: -Stormwater controls need to be installed to stabilize erosion along the access road and within the southeastern corner of the project area. This includes properly diverting stormwater flows, installation of BMPs, and stabilization of culvert inlets and outlets. All stormwater controls need to be selected, sized, installed, and maintained according to good engineering practices. Current practices and materials are not adequate. Corrective action date: 12/30/2021.</p>						<p>Date: 12/30/2021</p>
<p>Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693903915	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5593857