

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/07/2021

Submitted Date:

12/07/2021

Document Number:

700703637**FIELD INSPECTION FORM**
 Loc ID 412676 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415186	WELL	PR	02/01/2021	GW	045-18995	JOLLEY KP 412-9	PR
415406	WELL	PR	06/30/2010	GW	045-19054	JOLLEY KP 413-9	PR
415432	WELL	PR	05/31/2010	GW	045-19057	JOLLEY KP 44-8	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 12/7/2021 at approximately 1630, I, Inspector Scott Ramsey, conducted an emergency inspection at TEP KP 43-8, at Location # 412676 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed local fire department was packing up their hoses from extinguishing a tank that had caught on fire. TEP personal informed myself that roustabouts were in the process of replacing a tank burner when they had pulled the burner assembly away from tank the dense vapors from the tank opening settled in the secondary containment around the base of the tank and ignited. TEP personal also stated that one of the tank burners in the containment was still in operation when roustabouts were removing burner assembly. I had noticed that the combustor was shut in along with the separators. I saw that the vent line, that is tied into every tank and the combustor, on top of the tanks has no way to isolate the tanks, so any vapors in other tanks would be able to go straight to the tank they were working on. Also the crossover line valve from the tank next to the one that they were working on was open. The tank next to the fire had about 6 foot of condensate. No personal was injured. Fire department informed me that they had to use 2 ½ gallons of foam. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area and 411 water protection. During this inspection the following compliance issues were observed:

1. Extensive damage to tank, charred second tank, battery signage, secondary containment, etc. due to fire.
2. Possible impacted soil from tank containment that was melted.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Sign is not ledgible		
Corrective Action:	Replace battery signage	Date:	03/04/2022

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Containment was melted from tank fire			
Corrective Action:	Repair or install berms or other secondary containment devices			Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 415186 Type: WELL API Number: 045-18995 Status: PR Insp. Status: PRFacility ID: 415406 Type: WELL API Number: 045-19054 Status: PR Insp. Status: PRFacility ID: 415432 Type: WELL API Number: 045-19057 Status: PR Insp. Status: PR**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402890718	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5599566
700703638	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5599565