

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/11/2022

Submitted Date:

01/12/2022

Document Number:

700600351

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Kosola, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10705  
 Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
 Address: 1875 LAWRENCE ST STE 1150  
 City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>
Foutz, Paul		paul.foutz@state.co.us	<a href="#">Southeast Aquatics - Arkansas River Basin</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481394	SPILL OR RELEASE	AC	01/12/2022		-	Becks 41-16	EI

**General Comment:**

This is an environmental inspection to document status of Spill 481394. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site condition at the time of inspection. Investigation by operator is ongoing. This inspector observed no impacts to wildlife during inspection. Spill flowed into drainage that is considered Waters of the State. Drainage had no pooled or live water during inspection and only contained snow. Spilled produced water has been absorbed into soil along spill path.

**Operator reported:**

On January 10, 2022 at 1430, a spill was discovered at the Becks 41-15 well by an employee. The spill originated at the wellhead due to a broken 2" valve on the wellhead water line. The spill was immediately isolated by the employee and additional employees were notified to assess damage/spill volume. Initial estimations of spill volume are 53.4 bbls of produced water. The spill ran south 20 feet from the source at the wellhead, changed direction, flowed 110 feet northeast, entered a culvert, and flowed 60 feet south off location. The spill then flowed 410 feet south where it entered a dry arroyo which has been identified as waters of the state and high priority habitat

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment: Spill of 53.4 bbl of produced water occurred on 1/10/2022. See attached photos of flow path. No standing water from spill was observed during inspection. Produced water from spill that flowed off of the well location was absorbed into the soil. Operator has obtained soil samples from this area.

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 481394 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Less than 2-feet of freeboard

Corrective Action: Lower fluid level so at least two feet of freeboard exists per Rule 909.c.

Date: 01/12/2022

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700600352	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5630887">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5630887</a>