

FORM  
INSPRev  
X/20

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/28/2022

Submitted Date:

01/28/2022

Document Number:

693200922

## FIELD INSPECTION FORM

Loc ID \_\_\_\_\_ Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 1 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481322	SPILL OR RELEASE	AC	12/27/2021		-	Ryan Gulch Mud Can #2.0	AC

**General Comment:**

**Inspected Facilities**

Facility ID: 481322 Type: SPILL OR API Number: - Status: AC Insp. Status: AC

**Flowline**

#1	Type: Non-Well Site	1 of Lines
----	---------------------	------------

Flowline Description

Flowline Type: Non-Well Site Size: 4" Material: Other  
 Variance: Age: New Contents: Produced Water

Integrity Summary

Failures: Other Spills: Yes Repairs Made: Yes  
 Coatings: H2S: No Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: Root cause listed as equipment failure. 4" flexline, A recently installed flexline transferring production water developed a leak at the valve can. Reason for the leak is believed to be a pierced/crimped section of the flexline that occurred during installation.  
  
 Section of the flexline that caused the leak has been replaced. The failed section of pipe has been sent back to the manufacturer for forensic analysis to determine the cause of failure  
  
 Follow up with Integrity Inspector when Manufacturer has cause of failure

Corrective Action:

Date: