

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/27/2022

Submitted Date:

01/28/2022

Document Number:

693904163**FIELD INSPECTION FORM**Loc ID 326593 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10679Name of Operator: LOGOS OPERATING LLCAddress: 2010 AFTON PLACECity: FARMINGTON State: NM Zip: 87401**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		regulatory@logosresourcesllc.com	<a href="#">All Inspections 8/2/2021</a>
Rowley, Darren		drowley@logosresourcesllc.com	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258550	WELL	PR	10/09/2001	GW	067-08365	BONDAD 33-10 5A	PR

**General Comment:**

On 1/27/2022 Catherine Roy conducted a followup reclamation and stormwater inspection. During this inspection the following compliance issues were observed:

-Stormwater controls need to be installed to stabilize the southern diversion, erosional channeling on the well pad, and along the access road, especially at the culvert outlet near the well pad entrance. Stormwater controls need to be selected, sized, installed, monitored, and maintained according to good engineering practices. Corrective action is backdated to original corrective action date of 4/11/2021 to document duration of non-compliance, as original corrective action is not adequately addressed.

See below, and attached photos for additional detail.

Inspected Facilities				
Facility ID: 258550	Type: WELL	API Number: 067-08365	Status: PR	Insp. Status: PR

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective actions identified during the March 2021 reclamation inspection are not adequately addressed. Stormwater BMPs installed are not appropriate materials nor sized properly to stabilize erosion within the project area, and do not demonstrate good engineering practices. Specifically, accelerated erosion continues where concentrated stormwater flows off of the well pad, within the southern diversion, along the access road, and at the culvert along the access/near the well pad entrance.

Corrective Action: -Stormwater controls need to be installed to stabilize the southern diversion, erosional channeling on the well pad, and along the access road, especially at the culvert outlet near the well pad entrance. Stormwater controls need to be selected, sized, installed, monitored, and maintained according to good engineering practices. Corrective action is backdated to original corrective action date of 4/11/2021 to document duration of non-compliance.

Date: 04/11/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693904168	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5648140">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5648140</a>