

FORM  
6Rev  
11/20

## State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

402954582

Date Received:

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120

Contact Name: Christina Hirtler

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Phone: (720) 929-6301

Address: P O BOX 173779

Fax:

City: DENVER State: CO Zip: 80217-

Email: christina\_hirtler@oxy.com

**For "Intent" 24 hour notice required,**

Name: Revas, Robbie

Tel: (720) 661-7242

**COGCC contact:**

Email: robbie.revas@state.co.us

Type of Well Abandonment Report: ☒ Notice of Intent to Abandon ☐ Subsequent Report of Abandonment

API Number 05-123-20751-00

Well Name: CANNON

Well Number: 3-3A

Location: QtrQtr: NENW Section: 3 Township: 2N Range: 66W Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: WATTENBERG

Field Number: 90750

*Only Complete the Following Background Information for Intent to Abandon*

Latitude: 40.173072

Longitude: -104.765128

GPS Data: GPS Quality Value: 2.1 Type of GPS Quality Value: Date of Measurement: 10/30/2008

Reason for Abandonment: ☐ Dry ☒ Production Sub-economic ☐ Mechanical Problems☐ OtherCasing to be pulled: ☒ Yes ☐ No Estimated Depth: 825Fish in Hole: ☐ Yes ☒ No If yes, explain details belowWellbore has Uncemented Casing leaks: ☐ Yes ☒ No If yes, explain details below

Details:

**Current and Previously Abandoned Zones**

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7422	7440			
J SAND	7870	7940			
NIOBRARA	7150	7282			

Total: 3 zone(s)

**Casing History**

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	j-55	24	0	725	510	725	0	VISU
1ST	7+7/8	4+1/2	I-80	11.6	0	8031	480	8031	4190	CBL

### Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7800 with 2 sacks cmt on top. CIBP #2: Depth 7100 with 2 sacks cmt on top.

CIBP #3: Depth 260 with 80 sacks cmt on top. CIBP #4: Depth          with          sacks cmt on top.

CIBP #5: Depth          with          sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 5 sks cmt from 4493 ft. to 4430 ft.

Plug Type: CASING

Plug Tagged: ☐

Set 60 sks cmt from 2900 ft. to 2100 ft.

Plug Type: CASING

Plug Tagged: ☐

Set 60 sks cmt from 1850 ft. to 1050 ft.

Plug Type: CASING

Plug Tagged: ☐

Set 80 sks cmt from 260 ft. to 0 ft.

Plug Type: CASING

Plug Tagged: ☐

Set          sks cmt from          ft. to          ft.

Plug Type:         

Plug Tagged: ☐

Perforate and squeeze at 4523 ft. with 95 sacks. Leave at least 100 ft. in casing 4493 CICR Depth

Perforate and squeeze at 2900 ft. with 190 sacks. Leave at least 100 ft. in casing          CICR Depth

Perforate and squeeze at 1850 ft. with 190 sacks. Leave at least 100 ft. in casing          CICR Depth

(Cast Iron Cement Retainer Depth)

Set 120 sacks half in. half out surface casing from 825 ft. to 675 ft.

Plug Tagged: ☐

Set 80 sacks at surface

Cut four feet below ground level, weld on plate

Above Ground Dry-Hole Marker: ☐ Yes

☒ No

Set          sacks in rat hole

Set          sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered:          ft. of          inch casing

Surface Plug Setting Date:          Cut and Cap Date:         

Number of Days from Setting Surface Plug to Capping or Sealing the Well:         

\*Wireline Contractor:         

\*Cementing Contractor:         

Type of Cement and Additives Used:         

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

BMPs:  
Prior to commencing operations, KMG will post signs in conspicuous locations. The signs will indicate plugging and abandonment operations are being conducted, the well name, well, and the Operator's contact information. Signs will be placed so as not to create a potential traffic hazard.

Courtesy notifications will be sent to all parcel owners with building units within 1,500 feet of the location letting them know about our plugging and abandonment operations and providing contact information for Kerr McGee's response line and online resources.

In some cases, wellbore pressure drawdown operations may occur approximately 1-2 days prior to Move In Rig Up (MIRU) of the workover rig. This is conducted to allow for reduced time that the workover rig is needed on location. These operations will be conducted in accordance with Form 4 and/or Form 6 requirements.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed:         

Print Name: Christina Hirtler

Title: Regulatory

Date:         

Email: christina\_hirtler@oxy.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved. \_\_\_\_\_

COGCC Approved: \_\_\_\_\_

Date: \_\_\_\_\_

**CONDITIONS OF APPROVAL, IF ANY:** \_\_\_\_\_

Expiration Date: \_\_\_\_\_

**COA Type**

**Description**

--	--

**Attachment List**

**Att Doc Num**

**Name**

402955196	PROPOSED PLUGGING PROCEDURE
402955197	WELLBORE DIAGRAM

Total Attach: 2 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)