



00511704

PLUGGING PROCEDURE

WELL: Pelton Trust #1

1. Contractor is to notify Mr. Bob Van Sickle (719-336-2843) with the COGCC when plugging operations commence.
2. Spot ~~14~~²⁰ sx (~~14~~²⁰ cu. ft. slurry minimum) on top of existing CIBP set at 4375'. This will cover the perforations from 4294-98'.
3. Attempt to recover 5 1/2" casing above 2900'. Notify operator with depth of casing recovery as soon as it is known.
4. If casing is recovered below the top of the Cheyenne at 2529', spot a 40 sx cement plug from 2900' up or 1/2 in and 1/2 out of the casing stub, whichever is lower.
** IF CANNOT RECOVER AT LEAST 2700' OF CASING MUST PERF AT 2700' AND PUMP 40 SKS CMT*
5. Spot a 40 sx cement plug from ~~2430~~²⁵²⁰' up.
6. Spot a 40 sx cement plug from 2100' up.
7. Set a ~~40~~⁵⁰ sx cement plug across the 13 3/8" surface casing shoe at 353'. (1/2 in and 1/2 out)
8. Set a ~~10~~¹⁵ sx cement plug in the top of the surface casing.
9. Cut casing 4' below ground level and weld on a dated steel plate.
10. Remove surface equipment and restore location.