

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/25/2022

Submitted Date:

08/18/2022

Document Number:

699700326**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Heil, John 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10442Name of Operator: HUNTER RIDGE ENERGY SERVICES LLCAddress: 370 17TH STREET #1700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Morse, Casey		Casey.Morse@ovintiv.com	Senior Production Engineer

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446199	SPILL OR RELEASE	CL	06/16/2016		-	SPILL/RELEASE POINT 446199	EI

General Comment:

On July 25, 2022 COGCC Staff John Heil conducted an Environmental Inspection of the A27 Spill/Release ID 446199 Remediation Project #9748. The purpose of this inspection was to observe environmental drilling operations conducted by Oviniv personnel and to walk the gulch from the Water Collection / Treatment and Condensate Recovery System to SEEP 11 identified in the 2021 Quarter 4 Report for the A27 CDP Liquids Line Release Site Doc #402943781 (page 212/942).

Environmental**Spill/Remediation:**

Comment: COGCC staff walked the gulch from the Water Collection / Treatment and Condensate Recovery System to SEEP 11 identified in the 2021 Quarter 4 Report for the A27 CDP Liquids Line Release Site Doc #402943781 (page 212/942). During the walk of the gulch, potentially impacted material with a detectable hydrocarbon odor and a sheen was observed around SEEP PT10 (Doc #402943781) which is located on the east side of the gulch and the 12" poly line. The sheen was localized to the area surrounding the potentially impacted material around SEEP PT10 and the 12" poly line. A total of three kinks in the 12" poly line were observed at time of inspection. See attached Photo Log for details.

Corrective Action: Implement removal of free product and remediate soils, bedrock and groundwater to Table 915-1 concentration levels using the Protection of Groundwater Soil Screening Level Concentrations.

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403141278	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5833872
699700327	20220725 Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5833867