

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/25/2022

Submitted Date:

08/29/2022

Document Number:

696204020

FIELD INSPECTION FORMLoc ID 322317 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10539

Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP

Address: 760 HORIZON DRIVE STE 400

City: GRAND JUNCTION State: CO Zip: 81506

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gas, UtahGasCorp	970-693-6021	inspections@utahgascorp.com	Inspection mail box

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
322317	LOCATION	AC			-	FEDERAL-CARBONERA-67S104W 2NWNW	RI

General Comment:

On 8/25/2022, Reclamation Specialist Trujillo inspected Utah Gas Corp's Federal-Carbonera #1-2 Location in Garfield County, Colorado.

The following compliance issues were observed during this inspection:

-Stormwater

Refer to the "Location" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Lease Road:			
Type	Access		
comment:	It was observed in this inspection that stormwater, erosion control and stabilization BMPs are missing or insufficient along entire access road- erosion degradation and sediment transport evident. Road provides access to Locin Oil Corp's Government 1, Government 2, as well as Utah Gas Corp's Federal Carbonera 1-2 Locations. Corrective action is being provided to all 3 Locations.		
Corrective Action:	Comply with 1002.f.; Implement and maintain BMPs to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation on access road. Ensure controls are implemented in accordance with good engineering practices and maintained in proper functioning condition; regrading alone will not be sufficient to stabilize road and manage runoff.	Date:	09/13/2022

Overall Good: ☐**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 322317 Type: LOCATION API Number: - Status: AC Insp. Status: RI

COGCC Comments

Comment	User	Date
Collaborate with LOCIN OIL CORPORATION regarding necessary work to comply with 1002.f along access road, between the turn-off of CR 201 and the Fed.-Car. 1-2. Locin Oil remains responsible for maintenance of road leading north of the Fed.-Car. 1-2, to the Government #1 and #2 Locations.	trujilloam	08/29/2022
Refer to inspection nos. 696204016 and 696204018 for additional details.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696204021	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5842209