

FORM  
6Rev  
11/20

## State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Replug By Other Operator

Document Number:

403183995

Date Received:

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10651

Contact Name: Brian Stanley

Name of Operator: VERDAD RESOURCES LLC

Phone: (435) 6406426

Address: 1125 17TH STREET SUITE 550

Fax:

City: DENVER State: CO Zip: 80202

Email: bstanley@verdadresources.com

For "Intent" 24 hour notice required,

Name: Medina, Justin

Tel: (720) 471-0006

COGCC contact:

Email: justin.medina@state.co.us

Type of Well Abandonment Report: ☒ Notice of Intent to Abandon ☐ Subsequent Report of Abandonment

API Number 05-123-14809-00

Well Name: JORDAN-LOUSTAUNAU

Well Number: 34-10

Location: QtrQtr: NWSW Section: 34 Township: 1N Range: 65W Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: WATTENBERG

Field Number: 90750

## Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.007016

Longitude: -104.657432

GPS Data: GPS Quality Value: 1.3 Type of GPS Quality Value: PDOP Date of Measurement: 09/23/2022

Reason for Abandonment: ☐ Dry ☐ Production Sub-economic ☐ Mechanical Problems☒ Other Re-enter to re-plugCasing to be pulled: ☐ Yes ☐ No Estimated Depth:Fish in Hole: ☐ Yes ☐ No If yes, explain details belowWellbore has Uncemented Casing leaks: ☐ Yes ☐ No If yes, explain details below

Details:

## Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
D SAND	7830	7846	06/27/1996	B PLUG CEMENT TOP	7700

Total: 1 zone(s)

## Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	j55	24	0	261	180	261	0	VISU
1ST	7+7/8	4+1/2	j55	11.6	0	7978	107	7978	7160	CBL
	7+7/8	4+1/2	j55	Stage Tool	0	7978	130	1280	750	CBL

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set \_\_\_\_\_ 10 \_\_\_\_\_ sks cmt from \_\_\_\_\_ 6900 \_\_\_\_\_ ft. to \_\_\_\_\_ 6825 \_\_\_\_\_ ft. Plug Type: CASING Plug Tagged: ☐  
Set \_\_\_\_\_ 75 \_\_\_\_\_ sks cmt from \_\_\_\_\_ 1600 \_\_\_\_\_ ft. to \_\_\_\_\_ 850 \_\_\_\_\_ ft. Plug Type: CASING Plug Tagged: ☐  
Set \_\_\_\_\_ \_\_\_\_\_ sks cmt from \_\_\_\_\_ \_\_\_\_\_ ft. to \_\_\_\_\_ \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ \_\_\_\_\_ sks cmt from \_\_\_\_\_ \_\_\_\_\_ ft. to \_\_\_\_\_ \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ \_\_\_\_\_ sks cmt from \_\_\_\_\_ \_\_\_\_\_ ft. to \_\_\_\_\_ \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Perforate and squeeze at \_\_\_\_\_ 7075 \_\_\_\_\_ ft. with \_\_\_\_\_ 90 \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ 6900 \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ 1700 \_\_\_\_\_ ft. with \_\_\_\_\_ 115 \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ 1600 \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ 350 \_\_\_\_\_ ft. with \_\_\_\_\_ 90 \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set \_\_\_\_\_ 30 \_\_\_\_\_ sacks half in. half out surface casing from \_\_\_\_\_ 350 \_\_\_\_\_ ft. to \_\_\_\_\_ 0 \_\_\_\_\_ ft. Plug Tagged: ☐

Set \_\_\_\_\_ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing

Surface Plug Setting Date: \_\_\_\_\_ Cut and Cap Date: \_\_\_\_\_ Number of Days from Setting Surface Plug to Capping or Sealing the Well: \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_

\*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

A closed-loop, recirculating returns system will be used.

1. Provide 48 hr notice Form 42 to COGCC prior to rig up per Form 6 COA
2. Familiarize all personnel with allowed access to location and areas allowed to be disturbed.
3. Secure permission to access area and identify prospective well locations via satellite and survey data.
4. Verify well location and excavate well.
5. Once permission to begin work is secure, excavate area around well to sufficient size for safe access of casing, Verify casing size, cut off cap, weld on slip collar w/ wellhead and riser, set cellar ring and back-fill.
6. MIRU WO Rig, beam, doghouse, BOP, accumulator, rig pump, shaker tank, rig tank, 9.5ppg water-based mud, pipe float, 3-1/8" collars, 2-3/8" work string, power swivel.
7. Make up BHA; 2 3/8 EUE string, 2x 3-1/8" drill collars, Float, POBS, 3.75" roller-cone bit.
8. RIH and drill out cement from 0-1300'.
9. Wash/Ream inside 4.5" Casing to 7,700'. If depth is not achieved, call OGCC engineer.
10. Circulate and condition hole.
11. TOOH, Laydown BHA.
12. MIRU Wireline Truck and run CBL from 7700' to surface. There are conflicting reports of depths and volumes for squeezes/plugs of original P&A. If cement tops are different from "Before P&A" WBD, contact OGCC engineer and coordinate design adjustments. Confirm free pipe specifically between 7075-6800' and 1700-1330'.
13. Once TOC's are confirmed, MU perforating guns and RIH w/ 2' of 4spf squeeze hole guns and perforate bottom squeeze holes at 7075' (1 gun/4 holes), and top squeeze holes at 6825' (1 gun/4 holes). ). POOH and RDMO Wireline. MIRU cementers
14. MU 4.5" Cast iron cement retainer on 2-3/8" tbg and RIH to 6900'. Set retainer and establish circulation. Once circulation established, pump 100sks 15.8# Class G cement. Pump 90 sacks through retainer, unsting, and set 10sacks on top of retainer, and displace. POOH and LD 20 jts slow. RD cementers.
15. Valve around and reverse circulate to clean tubing.
16. POOH and LD tbg to 1600'. Stand back remaining tbg to derrick.
17. RU wireliners and RIH w/ 2' of 4spf squeeze hole guns and perforate bottom squeeze holes at 1700' (1 gun/4 holes), and top squeeze holes at 1330' (1 gun/4 holes). POOH and RDMO Wireline. MIRU cementers
18. MU 4.5" Cast iron cement retainer on 2-3/8" tbg and RIH to 1600'. Set retainer and establish circulation. Once circulation established, pump 190sks 15.8# Class G cement. Pump 115 sacks through retainer, unsting, and set 75 sacks on top of retainer, and displace. POOH w/ tubing. RD cementers.
19. POOH and LD to 600', reverse circulate tubing to clean up cement.
20. POOH and LD retainer stinger. Prep for surface plug.
21. RU wireliners and RIH w/ 1' of 4spf squeeze hole guns and perforate squeeze holes at 330' (1 gun/4 holes). POOH and RDMO Wireline. MIRU cementers.
22. Close blind rams and break circulation down 4.5" casing, and take returns up 8-5/8" surface casing. Once circulation established, begin circulating cement to surface (prescribed 120sx).
23. RDMO Cementers, Rig, and supporting equipment. Tidy location and prep for reclamation.
24. After 5 days, verify TOC is within 5' of surface. Top off if needed. Excavate cellar ring and wellhead, cut off casing 6' below ground level and weld on cap with full legal description welded onto plate. Back fill hole.
25. Reclaim location.
26. Submit Form 6 Subsequent and Form 42 for completion of COA.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Brian Stanley  
Title: Completion Engineer Date: \_\_\_\_\_ Email: bstanley@verdadresources.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_ Date: \_\_\_\_\_

**CONDITIONS OF APPROVAL, IF ANY:** \_\_\_\_\_ Expiration Date: \_\_\_\_\_

**COA Type** **Description**

--	--

### Attachment List

<u>Att Doc Num</u>	<u>Name</u>
403184040	SURFACE OWNER CONSENT
403184042	WELLBORE DIAGRAM
403184045	WELLBORE DIAGRAM
403184051	LOCATION PHOTO
403184053	PROPOSED PLUGGING PROCEDURE

Total Attach: 5 Files

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)