

# Inspection Photos

API: 071-09838

Operator: WAPITI OPERATING LLC

Inspection Date: 12/7/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09838 | Date: 12/7/2022

## Inspection Photos



**Photo 1.** The culvert outlet has eroded and needs to be repaired. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09838 | Date: 12/7/2022



## Inspection Photos



**Photo 2.** Facing toward the culvert outlet. The culvert outlet has eroded and needs to be repaired. Previous corrective action was not completed. BMP's must be installed per good engineering practice. (E.g. Rock outlet protection should include geotextile fabric)



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09838 | Date: 12/7/2022



## Inspection Photos



**Photo 3.** The next culvert along the road is also eroded at the culvert outlet with no outlet protection. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09838 | Date: 12/7/2022



## Inspection Photos



**Photo 4.** Facing southwest at the location. There is erosion occurring off the northeast side of the location. Additional BMP's need to be installed in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09838 | Date: 12/7/2022



## Inspection Photos



**Photo 5.** Facing northwest toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09838 | Date: 12/7/2022



## Inspection Photos



**Photo 6.** Facing east toward the location at the upper cut slope area. Stormwater run-on is causing erosion and is not properly diverted by the perimeter ditch. This area needs to be repaired and stabilized. Previous corrective action is not completed.

Red arrow points to 4.5 ft. shovel placed in the erosion channel.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09838 | Date: 12/7/2022



## Inspection Photos



**Photo 7.** Facing south toward the run-on ditch which is filled in with sediment causing erosion of the cut slope. Previous corrective action is not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09838 | Date: 12/7/2022



## Inspection Photos



**Photo 8.** There are additional erosion channels along the south side of the location. Previous corrective action is not completed. Red arrow points to 4.5 ft. shovel placed in the erosion channel.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09838 | Date: 12/7/2022