

PICEANCE HL

RG 01-02S-098W
RGU 41-1-298 Pad
RGU 531-1-298
WORKOVER

Operation Summary Report

Disclaimer: Although the information contained in this report is based on sound engineering practices, the copyright owner (s) does (do) not accept any responsibility whatsoever, in negligence or otherwise, for any loss or damage arising from the possession or use of the report whether in terms of correctness or otherwise. The application, therefore, by the user of this report or any part thereof, is solely at the user's own risk.

1 General

1.1 Customer Information

Company	PICEANCE HL
Representative	
Address	

1.2 Well Information

Well	RGU 531-1-298		
Project	RG 01-02S-098W	Site	RGU 41-1-298 Pad
Rig Name/No.		Event	WORKOVER
Start date	1/24/2023	End date	1/27/2023
Spud date	9/22/2011	UWI	RGU 531-1-298
Active datum	KB @6,594.0ft (above Mean Sea Level)		
Afe No./Description	/		

2 Summary

2.1 Operation Summary

Date	Time Start-End	Duration (hr)	Phase	Code	Sub	Class	MD from (ft)	Operation
1/24/2023	0:00 6:30	6.50		PROD	02	P		Well flowing to sales, Casing: 450psi Tubing: 400psi Braiden:450
	6:30 7:00	0.50		PROD	02	P		Rig inspection, safety meeting and daily operations discussion.
	7:00 9:00	2.00		MIRU	02	P		Spot in tubing trailers. and Beam sell down casing and braiden head, both fell at equal rates.
	9:00 11:00	2.00		MIRU	02	P		MIRU DUCO #3, Run pump lines and work on well head bolts and pins.
	11:00 11:45	0.75		WELL	02	P		Pump 20bbls kill tubing. and 60 bbl casing kill.
	11:45 12:30	0.75		MIRU	01	P		ND well head, NU BOP and test low and high. GOOD Test.
	12:30 13:00	0.50		POOH	02	P		Pull tubing hanger, string weight @ 68K and pulling free. and RU PRS tubing scanners.
	13:00 16:30	3.50		POOH	01	P		Scan out of hole with 140 joints. .
	16:30 17:30	1.00		PROD	02	P		Drain up pump and lines. secure well. dig out wellhead for casing repair.
1/25/2023	17:30 0:00	6.50		PROD	02	P		WSI
	0:00 6:30	6.50		WSI	01			WSI Casing: 370psi Tubing: 310psi Braiden: 370psi
	6:30 7:00	0.50		WSI	01			Rig inspection, Safety meeting and daily operations discussion.
	7:00 7:30	0.50		WELL	02	P		Pump 35 BBLs down CSG Pump 15 BBLs down TBG
	7:30 12:30	5.00		POOH	01	P		Scan and POOH Pull JNTS #120 to #346 Leave 10 JNTS in hole for tail string 48 yellow 83 Blue 216 Red Note: Scan report attached
	12:30 12:45	0.25		LOC	01	P		RD scanners
	12:45 13:00	0.25		RIH	01	P		Make up TSBP w/ setting tool
	13:00 15:00	2.00		RIH	01	P		RIH w/ 10 JNT tail string, TSBP and setting tool. Set TSBP @ 5283"
	15:00 15:30	0.50		TOOL	01	P		Pack of TSBP @ 5k, 10k, 15k, 20k, SW release off plug LD 1 joint
	15:30 16:30	1.00		PUMP	04	P		Role hole w/ 70 BBLs
	16:30 17:00	0.50		POOH	01	P		POOH with tubing 40 stands leave 41 stands in well
	17:00 17:30	0.50		WSI	01	P		secure well and drain up pump and lines. dig out around well head .
	17:30 0:00	6.50		WSI	02	P		WSI
1/26/2023	0:00 6:30	6.50		WSI	01	P		WSI Casing: 0psi Tubing: 0psi Braiden: 0psi
	6:30 7:00	0.50		WSI	01	P		Rig inspection, Safety Meeting and daily operations discussion.
	7:00 8:00	1.00		POOH	01	P		POOH with 40 stands and retrieving head.
	8:00 10:00	2.00		RDMO	01	P		RD work floor and N/D BOP's Removed B-section,
	10:00 10:15	0.25		21		P		Pulled a partial joint @ 19.10'

2.1 Operation Summary (Continued)

Date	Time Start-End	Duration (hr)	Phase	Code	Sub	Class	MD from (ft)	Operation
	10:15 10:45	0.50		FISH	02	P		R/U floor & tongs Make up 7 3/8" overshot with 4 1/2" grapple with 4 1/2" control
	10:45 11:30	0.75		RIH	01	P		RIH with 2 7/8" LH drillpipe, latched up to CSG top @ 20' Pull test over - shot 60k
	11:30 11:45	0.25		MIRU	01	P		MIRU DLD Wireline RIH with shot rod 71' Pulled up to 5k, Backed off CSG
	11:45 12:30	0.75		WELL	01	P		POOH with 1 jts 4 1/2" CSG tallied @ 43.18' putting CSG top @ 62.28'
	12:30 13:00	0.50						R/D DLD wireline crew Changed out handling equipment
	13:00 13:30	0.50		MIRU	02	P		Made first jt with new 4 1/2" P-110 RIH with 2 jts 4 1/2" P-110 CSG Tag top CSG @ 63' on jt 2
	13:30 14:15	0.75		RIH	01	P		Screw into casing string torque string up to 2650 ft/lbs (15 turns total) Pull test casing to 60K Pressure test casing to 2000psi and hold 15 min - good test
	14:15 14:30	0.25		WELL	01	P		Landed 4 1/2" CSG @ 55k, set slips, cut off & prepped casing Used total 2 jts new P-110 CSG @ 89.25' R/D floor & tongs
	14:30 15:30	1.00		WSI	01	P		N/U B-section, BOP's, Pressure test tbg head to 5k - good test Pressure test void to 10k - good test Pressure tested BOPs low & high test - good test R/U floor & tongs
	15:30 16:00	0.50		RIH	01	P		Make up 4 1/2" retriv head and RIH to TSBP @ 5283' Latch on to plug and release.
	16:00 16:30	0.50		POOH	01	P		POOH and stand back 43 stands
	16:30 17:00	0.50		WSI	01	P		Secure well. Winterized equipment Night capped rig tanks
	17:00 0:00	7.00		WSI	01	P		WSI
1/27/2023	0:00 6:30	6.50		WSI	01	P		WSI. Casing 370psi Tubing: 360psi Braiden: 0psi
	6:30 7:00	0.50		WSI	01	P		Rig inspection, Safety meeting and daily operations discussion.
	7:00 7:30	0.50		WELL	02	P		Pump 45 bbl casing kill
	7:30 8:30	1.00						POOH with TSBP LD tail string
	8:30 9:00	0.50		MIRU	05	P		MIRU PRS Hydrotesters. Make up BHA Notch collar. Seat nipple on botton tested joint. Pump 40bbl casing kill.
	9:00 17:00	8.00		RIH	01	P		Hydrotest in to 11894' did not tag. 260' past landing depth.
	17:00 17:30	0.50		POOH	01	P		POOH to landing depth @ 11,634.86' . 82% in the perms.
	17:30 17:45	0.25		WELL	01	P		Land tubing@ 11,634.86' and test hanger connection. Hanger 249 joints P-110 white band 40 joints N-80 yellow band 72 Joints N-80 Blue band New seat nipple Notch Collar 361 joints total in well.
	17:45 18:00	0.25		RDMO	02	P		RD PRS hydrotest truck.
	18:00 18:30	0.50						RD work floor and ND BOP, NU wellhead.
	18:30 19:00	0.50		WSI	01	P		Drain up pump and lines, well shut in.
	19:00 0:00	5.00						WSI