

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/15/2023

Submitted Date:

03/17/2023

Document Number:

708200054

FIELD INSPECTION FORM

Loc ID 317498 Inspector Name: Edwardson, Dylan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 76840
 Name of Operator: SCHNEIDER ENERGY SERVICES INC
 Address: P O BOX 889
 City: FORT MORGAN State: CO Zip: 80701

Findings:

- 4 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
SCHNEIDER, JEFF	970-867-9437	jeff@schneiderenergy.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238513	WELL	PA	06/21/2021	OW	123-05372	APRIL 12-14	RI
317498	LOCATION	AC			-	APRIL-67N60W 14SWNW	RI

General Comment:

This is a Stormwater Inspection for Location ID (317498) and also a follow-up inspection to FIR (Doc #708200033).

Inspected Facilities

Facility ID: 238513 Type: WELL API Number: 123-05372 Status: PA Insp. Status: RI

Facility ID: 317498 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [See "COGCC CCOMMENTS" section.](#)

Corrective Action: **Immediately install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Any impacted/eroded areas will need to be properly stabilized and reclaimed in accordance with Rule 1004, including impacts observed on adjacent land. Corrective action date is the date the location was observed out of compliance, as the location should be in compliance at all times.**

Date: 03/15/2023

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>Stormwater Comments:</p> <p>This location does not comply with Rule 1002.f. It appears a perimeter ditch and berm was constructed around the production areas with a sediment trap and water bar near the southwest corner. The perimeter berm isn't stabilized as it consists of loose/unconsolidated material that could become a potential source of pollution itself. There doesn't appear to be any stabilization around the in/out flows of the sediment trap and the water bar appears to divert stormwater around the perimeter berm and into the recently reclaimed areas. Further, eroded areas have not been properly stabilized and will require remedy, including reclamation, to any impacted areas both on and off location. BMPs are not sufficient to prevent further erosion or control sediment laden stormwater from exiting off location. Operator needs to install sufficient erosion and sediment control BMP in accordance with good engineering practices, immediately. Refer to attached inspection photos for additional detail and documentation.</p> <p>Note: Freshwater emergent wetland is approximately 600' south, and down gradient of location.</p>	edwardsond	03/17/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708200059	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6054954