

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2023

Submitted Date:

05/10/2023

Document Number:

696204923

FIELD INSPECTION FORMLoc ID 322479 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10539

Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP

Address: 760 HORIZON DRIVE STE 400

City: GRAND JUNCTION State: CO Zip: 81506

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccenforcement@state.co.us	
, Inspections	(970) 675-7928	inspections@utahgascorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210590	WELL	TA	08/01/2020	GW	045-06346	YOUNG CATTLE CO. 24-12	RI
322479	LOCATION	AC			-	YOUNG CATTLE CO.-66S104W 24NWSW	RI

General Comment:

On 5/8/2023, Reclamation Specialist Trujillo attempted to inspect Utah Gas Corp's Young Cattle Co 24-12 Location in Garfield County, Colorado.

This inspection is a follow-up to Inspection Nos. 696204014 and 696204449, to document compliance with the following corrective action: -Stormwater / Access

It was observed that the Location remains out of compliance with COGCC Rules and Corrective Actions

Refer to the "Stormwater" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities									
Facility ID:	210590	Type:	WELL	API Number:	045-06346	Status:	TA	Insp. Status:	RI
Facility ID:	322479	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
	Fail		Fail			

Comment: [See "COGCC Comments".](#)Corrective Action: [Comply with Rules 1002.e.\(1\), 1002.e.\(2\), 1002.e.\(4\) and 1002.f.\(2\).](#)

Date: 09/29/2022

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Salt Creek considered an Aquatic Native Species Conservation Waters; per conversations with CPW, Salt Creek is an important drainage for T&E and State special status fish species.	trujilloam	05/10/2023
STORMWATER/ACCESS ROAD Inspection #696204014 observed that stormwater has degraded the access road, preventing safe access to the Location. Inspection required Operator to comply with Rule 1002.f.; maintain access road; implement and maintain BMPs to stabilize access road, manage runoff and minimize further degradation. Operator submitted Resolution #403195476 stating CA Completed "Access Road Repaired". Inspection #696204449 observed that work to maintain the access road remained inadequate; erosion and degradation has persisted at the access road, and stream crossing. It was observed in this inspection that corrective actions at the access road have not been taken, or are inadequate; -Access road lacks a properly engineered stream crossing: Culverts at the stream crossing (~ 39.509427/-108.941081) have not been installed or maintained in accordance with good engineering practices; unable to find inlets; Salt Creek is actively flowing; flows are now channeled east of where the culverts and the former stream crossing are located, resulting in erosion degradation to the access road and additional sediment discharges into Salt Creek. -Stormwater and Erosion control BMPs to stabilize, as well as manage runoff in such a manner that minimizes erosion, transport of sediment offsite, and degradation remain missing or insufficient at the access road; erosion degradation has persisted. Pursuant to Rule 1002.f, Stormwater and Erosion control BMPs remain missing or insufficient, the road remains unsafe, and Location remains inaccessible as required by Rule 204.	trujilloam	05/10/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403399746	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6110358
696204924	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6110345