

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/17/2023

Submitted Date:

08/18/2023

Document Number:

708300798

**FIELD INSPECTION FORM**Loc ID 324459 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Energy, Gunnison		geops@oxbow.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211688	WELL	PR	10/01/2021	GW	051-06010	FEDERAL 10-90-32	PR

**General Comment:****COGCC Inspection Report Summary**

On 8/17/2023 at approximately 11:50, Compliance Inspector Matthew Morris conducted a follow-up inspection at GUNNISON ENERGY LLC, FEDERAL-610S90W/32SWSE at Location ID #324459 in Gunnison County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) Bradenhead valve is not accessible
- 2) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

<b>Lease Road:</b>			
Type	Main		
comment:	1) Lease road degradation near Clear Fork Creek crossing 2) Unprotected soil stockpiles near Clear Fork Creek crossing		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/(970) 874-7697

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead valve not visible due to water in wellhead cellar.		
Corrective Action:	Remove water from cellar and provide Bradenhead valve access to comply with Rule 419.a (2).	Date:	07/09/2023
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

<b>Inspected Facilities</b>				
Facility ID: 211688	Type: WELL	API Number: 051-06010	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Berms				
Ditches						
Mulching						
Seeding						
		Compaction				
		Other				Unprotected soil stockpiles
		Gravel				
Gravel						
Compaction						
		Rip Rap				
		Check Dams				
		Ditches				
Berms						
		Other				Lease road degradation
		Sediment Traps				

Comment: Channel erosion on south end of pad has been repaired. Grass seeding and mulch have been implemented as run-off BMPs.

Gravel tracking pad has been installed at entrance to location. Second entrance/exit has been blocked with barbed wire fencing and a berm.

1) Ditch runs parallel to lease road at location entrance/exit. No BMPs in place to minimize transportation of sediment from ditch onto lease road.

Corrective Action: 1) Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002.

Date: 07/14/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403502378	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6224997">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6224997</a>
708300807	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6224985">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6224985</a>