

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/03/2024

Submitted Date:

04/10/2024

Document Number:

714000631**FIELD INSPECTION FORM**Loc ID 484496 Inspector Name: Mcdonough, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10764Name of Operator: NUEVIDA RESOURCES LLCAddress: 5950 CEDAR SPRINGS RD STE #100City: DALLAS State: TX Zip: 75235**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pate, Richard	(303) 945-2868	dpate@nuevidaresources.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
484746	WELL	DG	07/24/2023		067-10037	Ardourel 33081718 3HL	RI
484747	WELL	DG	08/26/2023		067-10038	Ardourel 4HL	RI

General Comment:

On 4/3/2024 Reclamation Specialist Corey McDonough conducted a Reclamation and Storm water inspection at Nuevida Resources LLCs Ardourel 33081718 Location in La Plata County, Colorado. This is a follow up inspection to inspection doc #712700782.

During the inspection the following compliance issues were observed

- Storm water
- Debris/Trash

Refer to the "Storm water" and "Good-house keeping" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type

DEBRIS

Comment: Piping and concrete debris observed in the southern TUA pad.

Corrective Action: Comply with rule 606, remove and properly dispose of debris.

Date: 04/17/2024

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment: Corrective Action: Date: **Flaring:**

Type

Comment: Corrective Action: Date: **Location Construction**

Location ID: 484496

CDP: Comment: Corrective Action: Date: **Form 2A COAs:****Comment:**

Pursuant to COAs on form 4 #403461581 w/n 30 days of approval operator was required to 1. Provide updated data for the Form 2B regarding the changes to the water volumes used from each type of source (recycled produced water vs fresh water) 2. Provide an updated MLVT count and updated total on-site water storage volume 3) Provide an updated Oil and Gas Location acreage size (if reduced) 4. Provide an updated project schedule that resulted from the changes.

Forms and required information were required by 9/28/2023.

Unable to find records that forms and required information have been submitted.

Corrective Action: Comply with form 4 #403461581 COA.

Date: **Wildlife BMPs:****Comment:** Corrective Action: Date:

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
		Material Handling And Spill Prevention	No

Comments: Erosion BMPs: Pursuant to COA #18 per Form 2A 402672778, Operator appears to have installed a berm along the TUA pad perimeter; liner also appears to have been installed on the entire pad. Pursuant to the COA, a "three (3)-foot high polypropylene strong wall (aka muscle wall)" and liner is also required to be installed around MLVTs on the TUA pad. At time of inspection MLVTs, as well as the strong walls, have not been placed on the TUA.

Ensure BMPs are implemented pursuant to Form 2A COAs.

Other BMPs:

Corrective Action:

Date:

		Spill Response	No
--	--	----------------	----

Comments: Erosion BMPs:

Other BMPs:

Pursuant to COA #10 a sump is planned for the northeast corner of the pad. Sump was not observed during inspection.

Corrective Action:

Date:

Comment:

**Corrective
Action:**

Date:

On Site Inspection (305):Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities									
Facility ID:	484746	Type:	WELL	API Number:	067-10037	Status:	DG	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	484747	Type:	WELL	API Number:	067-10038	Status:	DG	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: [Revegetation is progressing in the interim reclamation areas.](#)**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment

Corrective Action

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment

Corrective Action

Date _____

1002c. PROTECTION OF SOILS _____

Comment

Corrective Action

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment

Corrective Action

Date _____

1003a. Waste and Debris removed? _____

Comment

Corrective Action

Date _____

Unused or unneeded equipment onsite? _____

Comment

Corrective Action

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment

Corrective Action

Date _____

Guy line anchors marked? _____

Comment

Corrective Action

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: Inspection doc #712700782 observed rill and gully erosion forming site wide with lacking and inadequate storm water BMPs and required compliance by 6/15/2023. It was observed in this inspection that cut/fill slope tracking in addition to sparsely distributed hydromulch/tackifier has facilitated degradation and continued rill/gully erosion site wide. Original CA has not been addressed. Original CA and date remains applicable. No CA date is being provided as this location is out of compliance for the same Rule.</p> <p>Corrective Action: Comply with rule 1002 Install or repair required BMPs.</p> <p>Date: _____</p>						
<p>Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403749489	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503061
714000661	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503060