

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/17/2024

Submitted Date:

11/01/2024

Document Number:

699700436

FIELD INSPECTION FORM

Loc ID 323887 Inspector Name: Heil, John On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1700 LINCOLN ST STE 3950
City: DENVER State: CO Zip: 80203

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Cholas, Nick		nick.cholas@state.co.us	
Toews, Wesley J	9703195683	wtoews@blm.gov	BLM West Slope
Bankert, Wayne		wbankert@laramie-energy.com	
Longworth, Mike		mike.longworth@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
469498	Produced Water Transfer System	AC	08/24/2021		-	Cascade Creek Water Transfer System	EI

General Comment:

[ECMC Environmental Inspection. Any corrective action\(s\) from previous inspections that have not been addressed are still applicable.](#)

Inspected Facilities

Facility ID: 469498 Type: Produced API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER Estimated Spill Volume: 35

Comment: See Spill/Release ID 488230 for more information. Spill/Release occurred within High Priority Habitats (HPH) (Effective July 15, 2024). ECMC staff John Heil and Nick Cholas conducted an Environmental Inspection of the spill/release area and observed an excavation of Laramie's 4" produced water line that had failed. Potentially impacted fluids adjacent to the 4" produced water were observed within the excavation. Livestock fencing was present on the northwest side of the excavation but did not completely enclose the excavation. Multiple stockpiles of potentially impacted material were placed adjacent to the excavation. BMPs to prevent contamination of stormwater, surface water, Groundwater, and soil were absent at time of inspection.

Corrective Action: Operator shall comply with Rule 913.b.(5).i and fence or cover open excavations to prevent access when sites are not attended. Operator shall comply with Rule 913.b.(5).iv and properly store, handle, and manage all E&P Waste to prevent contamination of stormwater, surface water, Groundwater, and soil. Operator shall comply with Rule 913.b.(5).v and incorporate Best Management Practices protective of the relevant wildlife species or habitat.

Date: _____

Reportable: YES GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700437	20241017 Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6770115