

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/10/2025

Submitted Date:

01/28/2025

Document Number:

717100056

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
 \_\_\_\_\_ Rollins, Grace \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 47120  
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
 Address: P O BOX 173779  
 City: DENVER State: CO Zip: 80217-

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>
Mickelson, Erik		Erik_Mickelson@oxy.com	<a href="#">Oxy Environmental</a>
Brown, Kari		kari.oakman@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
489008	SPILL OR RELEASE	CL			-	Weld CTY2/Klitz9-26A Facility	EI

**General Comment:**

[ECMC Environmental Field Inspection Report Summary](#)  
 Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 489008  
 Spill Name: Weld CTY2/Klitz9-26A Facility  
 Remediation Project #: 37457  
 Fac ID: 488191  
 Reported Date of Discovery: 01/06/2025  
 Date of Inspection: 01/10/2025

- Two excavations remain open with snow accumulation.
- Metal fencing surrounds both excavations.
- Gray staining observed within northern excavation.
- Flowline risers were are present within the southern excavation.
- Unmarked soil was stockpiled on location with inadequate stormwater BMPs.

See attached corrective actions. A Supplemental Form 27 is required.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>				
Type	Area	Volume		
OTHER				
Comment: <input type="text" value="Metal fencing surrounds the excavations."/>				
Corrective Action: <input type="text"/>			Date: _____	

**Venting:**

Yes/No	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

**Flaring:**

Type	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

**Inspected Facilities**

Facility ID: 489008 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Remediation Project No. 37457 was created for closure of the Weld CTY2/Klitz9-26A Facility. Two excavations remain open with snow accumulation. Metal fencing surrounds both excavations. Gray staining observed within northern excavation. Flowline risers were are present within the southern excavation. Quarterly reporting was required under Remediation Project No. 37457; the last Form 27 for this project was submitted 10/22/2024 (Document No. 403902648).

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt and maintain a quarterly reporting schedule (90 days). Operator shall provide an updated Form 27 for Remediation Project No. 37457. Date: 02/11/2025

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Spill/Remediation:**

Comment: Unmarked soil was stockpiled on location with inadequate stormwater BMPs.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C. Date: 02/11/2025

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404071726	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892608">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892608</a>
717100057	ECMC Photo Log - Weld CTY2/Klitz9-26A Facility	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892605">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6892605</a>