

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2025

Submitted Date:

05/08/2025

Document Number:

718100511

FIELD INSPECTION FORM

 Loc ID 427218 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 ECMC Operator Number: 10515
 Name of Operator: GUNNISON ENERGY LLC
 Address: 999 18TH STREET SUITE 1755N
 City: DENVER State: CO Zip: 80202
Findings:

- 6 Number of Comments
 2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Chamard, Megan		megan.chamard@state.co.us	
,		geops@oxbow.com	Inspection mail box
Gaasche, Emily		emily.gaasche@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427218	LOCATION	AC			-	DGU Federal 1289 Section 18 Pad	RI

General Comment:

On 5/6/2025, Western Reclamation Work Lead Trujillo conducted an interim reclamation inspection at Gunnison Energy's DGU Federal 1289 Section 18 Pad location in Gunnison County, Colorado.

This inspection is a followup to #696205086 and #696206393 to document compliance with the following corrective actions:
 -Containment BMP lacks integrity

It was observed in this inspection that the corrective action regarding containment integrity remains outstanding.

Refer to the "Location", "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				Inadequate
Comment: See "COGCC Comments" at the end of this report				
Corrective Action: Install/maintain secondary containment BMP; ensure BMP is sufficiently impervious to contain a spill or release.				Date: <input type="text"/>

Venting:

Yes/No	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Flaring:

Type	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Inspected Facilities

Facility ID: 427218 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Perennial vegetation over the interim areas appears to be progressing towards a uniform standard. However, it is noted that the species establishing appears to be a Brome-grass monoculture (such as smooth brome), and is not reflective of the vegetation observed within the adjacent reference areas; vegetation observed within the adjacent reference areas consist of species including Artemisia tridentata, Pascopyrum smithii, Leymus cinereus and various Astragalus, Oxytropis and Brassicaceae species.

Pursuant to 1003.e.(2), species seeded should be consistent with the adjacent plant community.

Corrective Action In accordance with Rule 210.a- submit, attached to a Form 4, documentation of consultation with the Surface Owner regarding the seed mixture, and provide the seed tags of the "Surface Owner provided seed mixture" used during interim reclamation.

Date 05/15/2025

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: **BMPs (Gravel/Compaction) to stabilize the working pad surface, and to minimize vehicle tracking/sediment transport is sparse and showing signs of disrepair; tracking/degradation becoming apparent. Maintenance advised.**

Continue to monitor/manage stormwater on the Location. Ensure BMPs remain in proper functioning condition pursuant to Rule 1002.f requirements.

Corrective Action: _____

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>TANK BATTERY- SECONDARY CONTAINMENT COMMENTS</p> <p>Operator Submitted Form 19 #403358735 on 3/30/2023 stating a produced water spill at the tank battery facility breached containment; Spill has been managed and resolved under Remediation Project #28376.</p> <p>Inspection #696205086 dated 07/10/2023 observed that Operator failed to take appropriate action to ensure any further spills/releases would remain in containment; secondary containment BMP at the battery was not sufficiently impervious to contain a spill or release; holes/tears remain within the secondary containment liner. Inspections required Operator to install/maintain secondary containment BMP, and to ensure BMP is sufficiently impervious to contain a spill or release.</p> <p>It was observed in this inspection that work to install or repair and maintain the BMP has not been performed, or has been insufficient; Hole in liner identified in previous inspections along the western wall of the containment measure has not been repaired.</p> <p>This CA has not been addressed and remains applicable.</p>	trujilloam	05/08/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718100512	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7041469