

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/04/2025

Submitted Date:

06/05/2025

Document Number:

694500779

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
NEIDEL, KRIS 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10779

Name of Operator: SCOUT ENERGY MANAGEMENT LLC

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------|---------|
| Fischer, Alex | | alex.fischer@state.co.us | |
| Christian, Cody | 970-902-0518 | Cody.Christian@scoutep.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|---------------------|--------|-------------|------------|-----------|---------------|-------------|
| 421610 | WELL | PR | | OW | 103-11858 | EMERALD 93X | EI |
| 489970 | SPILL OR RELEASE | AC | 05/02/2025 | | - | Emerald 93X | EI |

General Comment:

On 6/4/25 ECMC staff, Kris Neidel inspected the Emerald 93x and spill number 489970. The 93x well was PR at the time of inspection. The spill was reported as originating from the wellhead and fluid was contained to the bad by a tertiary location berm. . Any corrective actions issued by ECMC in other inspections remain valid. Weather was 75 degrees and partly cloudy. The following was observed: Fluid was inside the well cellar, It appeared that no fluid had left location, some salt staining was observed in the low part of the well pad, one area of hydrocarbon staining was observed (see photo #10) Corrective Actions: remove fluid from cellar. remove areas of observable hydrocarbon staining with a shovel and bucket (or equivalent) See attached photos.

| Inspected Facilities | | | | | | | | | |
|------------------------------------------------------------------------------------------|--------|-------|----------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 421610 | Type: | WELL | API Number: | 103-11858 | Status: | PR | Insp. Status: | EI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |
| Facility ID: | 489970 | Type: | SPILL OR | API Number: | - | Status: | AC | Insp. Status: | EI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |

| Environmental | | |
|--------------------------------------|------------------------------------------------------------------------------------------------------------------------------------|-------------------------|
| Spill/Remediation: | | |
| Comment: | one area of hydrocarbon staining was observed (see photo #10) | |
| Corrective Action: | Remove fluid from cellar. remove areas of observable hydrocarbon staining with a shovel and bucket (or equivalent) | Date: <u>06/19/2025</u> |
| Emission Control Burner (ECB): _____ | | |
| Comment: | _____ | |
| Pilot: _____ | Wildlife Protection Devices (fired vessels): _____ | |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 404231033 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7083869 |
| 694500780 | photo | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7083863 |