Stormwater Inspection

April 20, 2018

Operator: PETROSHARE CORPORATION- 10454

API: 05-039-06558

Inspection Document #: 682403504

Elbert County, CO

NWNW Section 21 T6S R64W

Chris Binschus
Reclamation Specialist, COGCC

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

Photo 1. Photo taken from the northwest battery location on November 3, 2017, facing East. Gully erosion evident and no observed BMPs have been implemented to control and mange stormwater erosion along any portion of the location.

Photo 2. Photo taken from the northwest battery location on April 20, 2018, facing East. Operator made repairs to the gully erosion and installed BMPs (i.e straw bales and berm). Berm BMP has been damaged due to vehicle traffic and is not in proper functioning condition.

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

11.03.2017 14:31

04.20.2018 08:47

Photo 3. Photo taken from the southern battery location on November 3, 2017, facing South. Photo illustrates the area at which stormwater runoff is leaving the southern location.

Photo 4. Photo taken from the southern battery location on April 20, 2018, facing South. Operator has installed BMPs (i.e straw bales).

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

Photo 5. Photo taken from the southern battery location on April 20, 2018, facing North. Photo illustrates berm BMP has been damaged due to vehicle traffic and is not in proper functioning condition.

Photo 6. Photo taken from the northern well location on April 20, 2018, facing West. Appears the Operator has installed BMPs to control erosion but all the BMPs have been damaged due to cattle. Operator may need to coordinate with the surface owner to exclude cattle around the oil and gas location.

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

Photo 7. Photo taken from the southern well location on April 20, 2018, facing West. See comments under Photo 6.