

PIT STATUS EVALUATION FORM

Facility ID: 115122

Pit Name: MYERS 12-3 1

Duplicate Record(s) Pit #



Legend

- Producing or Shut In Well
- ⚡ Temp Aban Well
- ⚡ Abandoned Well
- ⚡ Dry & Aban Well
- ⊛ Earthen Pit
- Culvert
- ✱ Backfilled Pit(s)
- Vault
- Fiberglass Tank
- Steel Tank(s)
- | Separator
- Wellhead
- Earthen Pit Extent
- Area of Disturbance
- Backfilled Pit Extent
- - - - Tank Fence

1:6,000

0 250 500 750 Feet

Image Source:
USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPANOPULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: RENEGADE OIL & GAS COMPANY LLC
 T: 6S R: 63W Sec: 3 QQ: SWNW 6th Meridian
 Latitude: 39.558107 Longitude: -104.438864 NAD83

County: Elbert, CO
 County Code: 039

Pit Status Evaluation

Active Form 15: Pit Permit NA Assoc. Well Seq No(s) 06547 (2-98) ^{PR}
 Other documentation _____
 Aerial photo verification _____

Closed Form 27: Remediation Workplan _____
 Form 4: Sundry Notice #394050 (2-12-1998) resume production
 Rule 903a.(2)B _____
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI
 Well API Seq #(s) _____
 Other documentation LIF #581128 (8-18-87), FIR #200124249 (9-13-07)

Abandoned Possible un-reclaimed pit(s) or adverse conditions, no closure docs Site Visit
 Unknown No Site Visit
 Add'l Review

Notes: LIF(8-18-87) #00 BBL Fiberglass Tank. No mention of Pit. FIR (2007) no mention of pit.
FIELD VERIFICATION! 6-3-2008: FIELD INSPECTOR VERIFIED NO PIT ON SITE.

PIT STATUS EVALUATION FORM

Facility ID: 115123

Pit Name: MYERS 32-3 2

Duplicate Record(s) Pit #



Legend

- Producing or Shut In Well
- ⚡ Temp Aban Well
- ⚡ Abandoned Well
- ⚡ Dry & Aban Well
- ☀ Earthen Pit
- Culvert
- ✱ Backfilled Pit(s)
- Vault
- Fiberglass Tank
- Steel Tank(s)
- | Separator
- Wellhead
- Earthen Pit Extent
- Area of Disturbance
- Backfilled Pit Extent
- - - - Tank Fence

1:6,000

Feet

0 250 500 750

Image Source:
USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPADOPULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: RENEGADE OIL & GAS COMPANY LLC
 T: 6S R: 63W Sec: 3 QQ: SWNE 6th Meridian
 Latitude: 39.558597 Longitude: -104.429139 NAD83

County: Elbert, CO
County Code: 039

Pit Status Evaluation

- Active** Form 15: Pit Permit NA Assoc. Well Seq No(s) 06584 (2-2-98)^{PR}
 Other documentation _____
 Aerial photo verification _____
- Closed** Form 27: Remediation Workplan _____
 Form 4: Sundry Notice _____
 Rule 903a.(2)B _____
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI
 Well API Seq #(s) WSIF #581132 (6-12-87) # WSIF #500141628 (5-8-1995)
 Other documentation FIR #200118813 (9-12-07)
- Abandoned** Possible un-reclaimed pit(s) or adverse conditions, no closure docs Site Visit
 Unknown No Site Visit
 Add'l Review

Notes: WSIF (1987) Skimpit. no earthen pit. WSIF (1995) indicates to "check for pit closure".
FIR (2007) no pit inventoried; one, 300 BBL Upright.
FIELD VISIT 6-4-2008: PIT CLOSED. Using fiberglass tank.

Facility ID 115123
Well API 05-039-06
Well API 05-039-06587

Myers 32-3 2 & 3
Myers 32-3 2
Myers 21-3 3

June 4, 2008



Photo 1. Covered fiberglass water tank and lease sign



Photo 2. Separator on battery site for Myers 32-3 2

Facility ID 115123
Well API 05-039-06
Well API 05-039-06587

Myers 32-3 2 & 3
Myers 32-3 2
Myers 21-3 3

June 4, 2008



Photo 3. Myers 32-3 2 wellhead

PIT STATUS EVALUATION FORM

Facility ID: 115126

Pit Name: VETTER 1-9-6-63K

Duplicate Record(s) Pit #



Legend

- Producing or Shut In Well
- ⚡ Temp Aban Well
- ⚡ Abandoned Well
- ⊙ Dry & Aban Well
- ⊙ Earthen Pit
- Culvert
- * Backfilled Pit(s)
- Vault
- Fiberglass Tank
- Steel Tank(s)
- | Separator
- Wellhead
- Earthen Pit Extent
- Area of Disturbance
- Backfilled Pit Extent
- - - - Tank Fence

1:6,000

0 250 500 750 Feet

Image Source:
USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPANOPULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: RENEGADE OIL & GAS COMPANY LLC
 T: 6S R: 63W Sec: 9 QQ: NENE 6th Meridian
 Latitude: 39.547347 Longitude: -104.443464 NAD83

County: Elbert, CO
County Code: 039

Pit Status Evaluation

Active Form 15: Pit Permit NA Assoc. Well Seq No(s) 06528
 Other documentation _____
 Aerial photo verification _____

Closed Form 27: Remediation Workplan _____
 Form 4: Sundry Notice _____
 Rule 903a.(2)B _____
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI
 Well API Seq #(s) _____
 Other documentation FIR (1995) _____

Abandoned Possible un-reclaimed pit(s) or adverse conditions, no closure docs Site Visit
 Unknown No Site Visit
 Add'l Review

Notes: Common Use battery tank site with Vetter #2 (05-039-06555)
FIR (1995) requested to backfill pit & replace w/cement vault for permit skip pit
FIELD VISIT 6-3-2008: PIT BACKFILLED

PIT STATUS EVALUATION FORM

Facility ID: 115133

Pit Name: RUNNING CREEK 15-5

Duplicate Record(s) Pit #

115066, 111257, 111258
115134, 115135, 115180



Legend

- Producing or Shut In Well
- ⊕ Temp Aban Well
- ⊖ Abandoned Well
- ⊗ Dry & Aban Well
- ⊙ Earthen Pit
- Culvert
- * Backfilled Pit(s)
- Vault
- Fiberglass Tank
- Steel Tank(s)
- | Separator
- Wellhead
- Earthen Pit Extent
- Area of Disturbance
- Backfilled Pit Extent
- - - Tank Fence

1:6,000

0 250 500 750 Feet

Image Source:
USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPADOPULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: THOMAS OPERATING COMPANY INC
T: 6S R: 64W Sec: 15 QQ: SWNW 6th Meridian
Latitude: 39.529674 Longitude: -104.548618 NAD83

County: Elbert, CO
County Code: 039

Pit Status Evaluation

Active Form 15: Pit Permit NA Assoc. Well Seq No(s) 06476
 Other documentation _____
 Aerial photo verification _____

Closed Form 27: Remediation Workplan _____
 Form 4: Sundry Notice _____
 Rule 903a.(2)B _____
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI
Well API Seq #(s) _____
 Other documentation LIE (1987) "no earthen pits but guess there is a large UST"

Abandoned Possible un-reclaimed pit(s) or adverse conditions, no closure docs Site Visit
 No Site Visit
 Add'l Review

Unknown

Notes: Common Use with Running Creek 15-3, 15-6, 15-5 battery tank site.
FIELD VISIT 6-3-2008: PIT BACKFILLED

Facility ID 115133
Well API 05-039-06476
Well API 05-039-06480
Well API 05-039-06509

Running Creek 15-3, 15-5 & 15-6
Running Creek 15-5
Running Creek 15-3
Running Creek 15-6

June 3, 2008



Photo 1. Lease sign for Running creek 15-3 and former pit site beyond berm



Photo 2. Looking southwest showing recently backfilled pit inside fence

PIT STATUS EVALUATION FORM

Facility ID: 115141

Pit Name: COGGINS 1-10

Duplicate Record(s) Pit #



Legend

- Producing or Shut In Well
- ⚡ Temp Aban Well
- ⚡ Abandoned Well
- ⊙ Dry & Aban Well
- ⊙ Earthen Pit
- Culvert
- * Backfilled Pit(s)
- Vault
- Fiberglass Tank
- Steel Tank(s)
- | Separator
- Wellhead
- Earthen Pit Extent
- Area of Disturbance
- Backfilled Pit Extent
- - - Tank Fence

1:6,000

0 250 500 750 Feet

Image Source:
USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPADOPULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: SMITH ENERGY CORP
 T: 6S R: 64W Sec: 10 QQ: SWSW 6th Meridian
 Latitude: 39.536938 Longitude: -104.547805 NAD83

County: Elbert, CO
 County Code: 039

Pit Status Evaluation

Active Form 15: Pit Permit #581286 (1982) new Assoc. Well Seq No(s) 06383 (9-5-81) PR
 Other documentation FIR # 441047 (6-20-95)
 Aerial photo verification

Closed Form 27: Remediation Workplan _____
 Form 4: Sundry Notice _____
 Rule 903a.(2)B _____
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI
 Well API Seq #(s) _____
 Other documentation FIR # 20088218 (1-30-06) no pit found

Abandoned Possible un-reclaimed pit(s) or adverse conditions, no closure docs Site Visit
 Unknown No Site Visit
 Add'l Review

Notes: FIR(1995) "production pit doesn't have screen over it - small amount of water"
FIELD VISIT 6-3-2008: no sign of pit

300 BBL upright or fiberglass tank offsite?

PIT STATUS EVALUATION FORM

Facility ID: 115151

Pit Name: NORDMAN TRUST 32-20

Duplicate Record(s) Pit #

115103



Legend

- Producing or Shut In Well
- ♁ Temp Aban Well
- ♁ Abandoned Well
- ⊛ Dry & Aban Well
- ⊛ Earthen Pit
- Culvert
- ✱ Backfilled Pit(s)
- Vault
- Fiberglass Tank
- Steel Tank(s)
- | Separator
- Wellhead
- Earthen Pit Extent
- Area of Disturbance
- Backfilled Pit Extent
- - - Tank Fence

1:6,000

0 250 500 750 Feet

Image Source:
USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPANOPULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: CRIMSON EXPLORATION OPERATING INC
 T: 6S R: 64W Sec: 20 QQ: SWNE 6th Meridian
 Latitude: 39.51382 Longitude: -104.574565 NAD83

County: Elbert, CO
 County Code: 039

Pit Status Evaluation

- Active Form 15: Pit Permit NA Assoc. Well Seq No(s) 06502 (5-22-08)^{SI}
 Other documentation FIR # 427959 (10-10-96)
 Aerial photo verification
- Closed Form 27: Remediation Workplan _____
 Form 4: Sundry Notice _____
 Rule 903a.(2)B _____
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI
 Well API Seq #(s) _____
 Other documentation _____
- fiberglass tank*
- Abandoned Possible un-reclaimed pit(s) or adverse conditions, no closure docs Site Visit
 Unknown No Site Visit
 Add'l Review

Notes: Common Battery Tank Site for Nordman Trust 42-20X & 33-20
FIR (1996) "earthen pit w/ screen needs repair"
FIELD VISIT 6-3-2008: NO SIGN OF PIT, PIT BACKFILLED

Facility ID 115151 Nordman Trust 41-20, 41-20X, 33-20 & 32-20

June 3, 2008

Well API 05-039-06524
Well API 05-039-06553
Well API 05-039-06541
Well API 05-039-06524

Nordman Trust 32-20
Nordman Trust 41-20
Nordman Trust 42-20X
Nordman Trust 33-20




Photo 1. Battery tanks and lease signs; fiberglass tank is southeast of tanks



Photo 2. Battery tanks and lease signs

Facility ID 115151 Nordman Trust 41-20, 41-20X, 33-20 & 32-20

June 3, 2008

Well API 05-039-06524

Nordman Trust 32-20

Well API 05-039-06553

Nordman Trust 41-20

Well API 05-039-06541

Nordman Trust 42-20X

Well API 05-039-06524

Nordman Trust 33-20



Photo 3. Battery tanks and lease signs

PIT STATUS EVALUATION FORM

Facility ID: 115160

Pit Name: WHITEHEAD 4-13

Duplicate Record(s) Pit #



Legend

- ★ Producing or Shut In Well
- ⚡ Temp Aban Well
- ⚡ Abandoned Well
- ⚡ Dry & Aban Well
- ★ Earthen Pit
- Culvert
- ★ Backfilled Pit(s)
- Vault
- Fiberglass Tank
- Steel Tank(s)
- | Separator
- Wellhead
- Earthen Pit Extent
- Area of Disturbance
- Backfilled Pit Extent
- - - Tank Fence

1:6,000

0 250 500 750 Feet

Image Source:
USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPADOPULOS & ASSOCIATES, INC.

COGCC Database Information

Status: CL Owner: RENEGADE OIL & GAS COMPANY LLC
 T: 6S R: 62W Sec: 4 QQ: SWSW 6th Meridian
 Latitude: 39.551063 Longitude: -104.3446 NAD83

County: Elbert, CO
 County Code: 039

Pit Status Evaluation

Active Form 15: Pit Permit NA Assoc. Well Seq No(s) 06260 (4-18-02)^{PR}
 Other documentation FIR# 444 542 (5-6-1996)
 Aerial photo verification

Closed Form 27: Remediation Workplan _____
 Form 4: Sundry Notice _____
 Rule 903a.(2)B _____
 Evidence pit(s) existed, no closure docs & well not PR, AC or SI
 Well API Seq #(s) _____
 Other documentation _____

Abandoned Possible un-reclaimed pit(s) or adverse conditions, no closure docs Site Visit
 Unknown No Site Visit
 Add'l Review

Notes: LIF(1987) 1250 GAL SKIM TANK & 30'x30' pit
FIELD VISIT 6-4-2008: EARTHEN PIT & CONCRETE VAULT FOUND WITH
OIL SATURATED SOILS & VEGETATION DISTURBANCE TO SOUTHEAST. PIT COVER
UNSATISFACTORY.



Photo 1. Whitehead 4-13 wellhead



Photo 2. Looking south at vertical separator



Photo 3. Looking southwest at 200 BBL tank



Photo 4. Covered earthen pit and concrete vault



Photo 5. Looking northwest at buried concrete vault and wellpad



Photo 6. Earthen pit

PIT STATUS EVALUATION FORM

Facility ID: 115172

Pit Name: RUNNING CREEK STATE 16, 14, 6

Duplicate Record(s) Pit #

111261, 115174, 115173



Legend

- Producing or Shut In Well
- ⊗ Temp Aban Well
- ⊗ Abandoned Well
- ⊗ Dry & Aban Well
- ⊗ Earthen Pit
- Culvert
- ★ Backfilled Pit(s)
- Vault
- Fiberglass Tank
- Steel Tank(s)
- | Separator
- Wellhead
- Earthen Pit Extent
- Area of Disturbance
- Backfilled Pit Extent
- - - Tank Fence

1:6,000

0 250 500 750 Feet

Image Source:
USDA National Agricultural Imagery Program (NAIP), 2006

S.S. PAPADOPULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: SMITH ENERGY CORP
 T: 6S R: 64W Sec: 16 QQ: SWSW 6th Meridian
 Latitude: 39.522252 Longitude: -104.569267 NAD83

County: Elbert, CO
 County Code: 039

Pit Status Evaluation

Active Form 15: Pit Permit NA Assoc. Well Seq No(s) 06510 #6, 06588 #14, 06574 #16

Other documentation _____

Aerial photo verification _____

Closed Form 27: Remediation Workplan _____

fiberglass tank Form 4: Sundry Notice _____

Rule 903a.(2)B _____

Evidence pit(s) existed, no closure docs & well not PR, AC or SI

Well API Seq #(s) _____

Other documentation FIR #200 _____

Abandoned Possible un-reclaimed pit(s) or adverse conditions, no closure docs Site Visit

Unknown No Site Visit

Add'l Review

Notes: Common Use Battery Tank Site for Running Creek State #16, #14, #6
UF (1987) 30'x30' skimpit. FIR (1996) "earthen pit w/screen, oil & H₂O in pit"
FIELD VISIT 6-3-2008: NO SIGN OF PIT. PIT BACKFILLED.

Facility ID 115172
Well API 05-039-06574
Well API 05-039-06510
Well API 05-039-06588

Running Creek 16, 14 & 6
Running Creek 16
Running Creek 6
Running Creek 14

June 3, 2008



Photo 1. Tank battery sign



Photo 2. Covered fiberglass tank

Facility ID 115172
Well API 05-039-06574
Well API 05-039-06510
Well API 05-039-06588

Running Creek 16, 14 & 6
Running Creek 16
Running Creek 6
Running Creek 14

June 3, 2008



Photo 3. Fiberglass tank and berm