

NW SEC. 10
3/4" ALUM. CAP
LS 16425

N 89°26'36" E 5316.54'

NW SEC. 11
3/4" ALUM. CAP
LS 11399

N 00°05'58" E 2639.37'

W/4 SEC. 11
3/4" ALUM. CAP
LS 11399

N 01°07'10" E 2640.12'

SW SEC. 10
3/4" ALUM. CAP
LS 16415

S 89°27'35" W 5366.26'

SW SEC. 11
CALC'D BY DOUBLE
PROPORTIONATE
MEASUREMENTS

N 89°17'59" E 2620.71'

NOTES:
THIS IS A DIRECTIONAL WELL.
BH LOCATION TO BE 2140' FSL & 500' FEL
BH LOCATION PROVIDED BY CLIENT.
LAND SURFACE USE-OPEN FIELD
TWINNING PROPOSED WELL FRICO 33-11
TO BE 16' S
PROPOSED WELL FRICO 33-11 TO BE
2327' FSL & 1676' FWL
EXISTING WELL FRICO 12-11 IS 50' SW
SEE ATTACHED MAP FOR ADDITIONAL
IMPROVEMENTS WITHIN 400'.

N 89°19'54" E 2723.11'

N 1/4 SEC. 11
3/4" ALUM. CAP
LS 13155

E 1/4 SEC. 11
3/4" ALUM. CAP
LS 12374

S 00°23'16" E 2678.58'

S 07°35'00" W 2675.49'

SE SEC. 11
3/4" ALUM. CAP
LS 22098

FRICO 9-10A

FRICO 12-11

FRICO 33-11

BH- 2140' FSL
500' FEL

1676'

S 89°30'21" W 2190'

2345'

SURFACE LOCATION
GROUND ELEVATION= 4779'
NAD83
LATITUDE= 40.238986°
LONGITUDE= 104.633937°

BOTTOM HOLE LOCATION
NAD83
LATITUDE= 40.238485°
LONGITUDE= 104.641755°

PDOP= 2.32
GPS OPERATOR: TRAVIS KRAICH

S 1/4 SEC. 11
CALCULATED FROM
WITNESS CORNER

WITNESS CORNER
3/4" ALUM. CAP
LS 22098

NOTICE: ACCORDING TO COLORADO LAW YOU MUST COMMENCE ANY LEGAL ACTION BASED UPON ANY DEFECT IN THIS SURVEY WITHIN THREE YEARS AFTER YOU FIRST DISCOVER SUCH DEFECT. IN NO EVENT MAY ANY ACTION BASED UPON ANY DEFECT IN THIS SURVEY BE COMMENCED MORE THAN TEN YEARS FROM THIS SAID DATE OF THIS CERTIFICATION SHOWN HEREON.