



FORM 19 Rev 6/99

State of Colorado Oil and Gas Conservation Commission



FOR OGCC USE ONLY
Spill report taken by:
FACILITY ID:

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303)894-2100 Fax:(303)894-2109

SPILL/RELEASE REPORT

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: OXY USA WTP LP OGCC Operator No: 66571
Address: 760 Horizon Drive, Suite 101
City: Grand Junction State: CO Zip: 81506
Contact Person: Alonzo Hernandez
Phone Numbers: No: 970.263.3609 Fax: 970.263.3694 E-Mail: alonzo_hernandez@oxy.com

DESCRIPTION OF SPILL OR RELEASE

Date of Incident: 12/08/2010 Facility Name & No.: 620-43-32 / 335456 = location ID
Type of Facility (well, tank battery, flow line, pit): tank battery
Well Name and Number: NA
API Number: NA 045-13486
Specify volume spilled and recovered (in bbls) for the following materials:
Oil spilled: ~130 Oil recov'd: Water spilled: ~170 bbl Water recov'd: ~10 bbl Other spilled: Other recov'd:
Ground Water impacted? [] Yes [X] No Surface Water impacted? [] Yes [X] No
Contained within berm? [] Yes [X] No Area and vertical extent of spill: TBD x
Current land use: Rangeland Weather conditions: cool, overcast
Soil/geology description: Happle-Rock outcrop association, 25% to 65% slopes
IF LESS THAN A MILE, report distance IN FEET to nearest.... Surface water: ~270' wetlands: NA buildings: NA
Livestock: NA water wells: NA Depth to shallowest ground water: ~70'
Cause of spill (e.g., equipment failure, human error, etc.): human error Detailed description of the spill/release incident:
Because of valve misalignment, fluids from the water gathering line entered into the 620-43-32 tanks resulting in a produced water and a condensate tank overflow into and adjacent to the unlined secondary containment.

CORRECTIVE ACTION


Describe immediate response (how stopped, contained and recovered):
The water gathering valve was fully closed and locked out to prevent reoccurrence. A water hauler extracted the free fluids from the secondary containment and drew the tank levels down.
Describe any emergency pits constructed:
None were constructed.
How was the extent of contamination determined:
Automation data.
Further remediation activities proposed (attach separate sheet if needed):
Currenty under investigation. Form 27 to follow.
Describe measures taken to prevent problem from reoccurring:
Currenty under investigation.

OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Table with 5 columns: Date, Agency, Contact, Phone, Response. Row 1: 12/17/10, COGCC, Chris Canfield, (970) 216-6832, Left Message

Spill/Release Tracking No: 2213208



Location of Spill

620-43-32 Pad

20