


<b>FORM</b> <b>6</b> Rev 12/05	State of Colorado <b>Oil and Gas Conservation Commission</b> 1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109				DE	ET	OE	ES
	Date Received: <div style="text-align: center;">03/21/2011</div>							
	Document Number: <div style="text-align: center;">1634442</div>							

**WELL ABANDONMENT REPORT**

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.  
 A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: <u>100128</u>	Contact Name: <u>ERICK BENISH</u>
Name of Operator: <u>VISTA OPERATING INC</u>	Phone: <u>(970) 630-5723</u>
Address: <u>61 MCMURRAY RD STE 300</u>	Fax: _____
City: <u>PITTSBURGH</u> State: <u>PA</u> Zip: <u>15241</u>	Email: _____
For "Intent" 24 hour notice required, COGCC contact: Name: <u>HORTON, COLBY</u> Tel: <u>(970) 467-2517</u> Email: <u>colby.horton@state.co.us</u>	

API Number	<u>05-125-10051-00</u>		
Well Name:	<u>K-Y PLETCHER</u>	Well Number:	<u>31-34</u>
Location:	QtrQtr: <u>NWNE</u>	Section: <u>34</u>	Township: <u>3N</u> Range: <u>48W</u> Meridian: <u>6</u>
County:	<u>YUMA</u>		
Field Name:	<u>WHISPER</u>	Field Number:	<u>92400</u>

☒ Notice of Intent to Abandon
 ☐ Subsequent Report of Abandonment

*Only Complete the Following Background Information for Intent to Abandon*

Latitude: 40.188524 Longitude: -102.725401

GPS Data:

Data of Measurement: 10/06/2006 PDOP Reading: 2.9 GPS Instrument Operator's Name: DAVID KUNOVIC

Reason for Abandonment: ☐ Dry ☒ Production for Sub-economic ☐ Mechanical Problems

☐ Other \_\_\_\_\_

Casing to be pulled: ☒ Yes ☐ No Top of Casing Cement: \_\_\_\_\_

Fish in Hole: ☐ Yes ☐ No If yes, explain details below \_\_\_\_\_

Wellbore has Uncemented Casing leaks: ☐ Yes ☐ No If yes, explain details below \_\_\_\_\_

Details: \_\_\_\_\_

Current and Previously Abandoned Zones					
Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
NIOBRARA	2858	2888			
Total: 1 zone(s)					

Casing History								
Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	9+7/8	7		417	75	417	0	
1ST	6+1/4	4+1/2		3,012	110	3,012	2,070	

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 2808 with 2 sacks cmt on top. CIPB #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
 CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIPB #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
 CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
 Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
 Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
 Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
 Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged: ☐

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
 Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
 Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 35 sacks half in. half out surface casing from 317 ft. to 517 ft. Plug Tagged: ☐

Set 10 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Plugging Date: \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No \*ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: DAVID NICKLAS

Title: VICE PRESIDENT Date: 3/14/2011 Email: DNICKLAS@VISTARESOURCES.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SUTPHIN, DIRK Date: 4/12/2011

**CONDITIONS OF APPROVAL, IF ANY:** \_\_\_\_\_ Expiration Date: 10/11/2011

- 1) Provide 24 hour notice of MIRU to Colby Horton at 970-467-2517 or e-mail at colby.horton@state.co.us.
- 2) Tag shoe plug.

### Attachment Check List

Att Doc Num	Name
1634442	WELL ABANDONMENT REPORT (INTENT)

Total Attach: 1 Files

IMPORTANT: SOME DATA FIELDS HAVE BEEN MODIFIED.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)