

FORM
6

Rev
12/05

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Date Received:
10/12/2011

Document Number:
2285072

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: <u>82470</u>	Contact Name: <u>ROSCOE mendenMENDENHALL</u>
Name of Operator: <u>STELBAR OIL CORP INC</u>	Phone: <u>(316) 440-7605</u>
Address: <u>1625 N WATERFRONT PKWY #200</u>	Fax: <u>(316) 264-0592</u>
City: <u>WICHITA</u> State: <u>KS</u> Zip: <u>67206-</u>	Email: <u>ROSCOE@STELBAR.COM</u>
For "Intent" 24 hour notice required,	Name: <u>HORTON, COLBY</u> Tel: <u>(970) 467-2517</u>
COGCC contact:	Email: <u>colby.horton@state.co.us</u>

API Number <u>05-121-09585-00</u>	Well Number: <u>A-2</u>
Well Name: <u>CHRISTIANSON</u>	
Location: QtrQtr: <u>NENE</u> Section: <u>11</u> Township: <u>3S</u> Range: <u>49W</u> Meridian: <u>6</u>	
County: <u>WASHINGTON</u>	Federal, Indian or State Lease Number: _____
Field Name: <u>ABARR</u>	Field Number: <u>200</u>

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.813224 Longitude: -102.823197

GPS Data:
Date of Measurement: 08/21/2007 PDOP Reading: 2.4 GPS Instrument Operator's Name: DAVID KUNOVIC

Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____

Casing to be pulled: Yes No Top of Casing Cement: _____

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
NIOBRARA	2752	2788			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	275	250	275	0	
1ST	7+7/8	4+1/2	9.5	2,984	200	2,984	2,000	

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 2720 with 2 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 325 ft. with 200 sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:
 Set 50 sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____
 *Wireline Contractor: _____ *Cementing Contractor: _____
 Type of Cement and Additives Used: _____
 Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: ROSCOE MENDENHALL
 Title: VICE PRESIDENT OPERATIONS Date: 10/7/2011 Email: ROSCOE@STELBAR.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SUTPHIN, DIRK Date: 10/14/2011

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: 4/13/2012

- 1) Provide 24 hour notice of MIRU to Craig Quint at 719-767-8939 or e-mail at craig.quint@state.co.us.
- 2) Tag shoe plug. Surface plug from 50' up in annulus and in casing.

Attachment Check List

Att Doc Num	Name
2285072	FORM 6 INTENT SUBMITTED
2285073	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

User Group	Comment	Comment Date

Total: 0 comment(s)