

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

12/18/2012

Document Number:

667500096

Overall Inspection:

Unsatisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>234109</u>	<u>316986</u>		<u>AXELSON, JOHN</u>

Operator Information:OGCC Operator Number: 52530 Name of Operator: MAGPIE OPERATING, INCAddress: 2707 SOUTH COUNTY RD 11City: LOVELAND State: CO Zip: 80537**Contact Information:**

Contact Name	Phone	Email	Comment
Warner, Ryan	(970) 669-6308	magpieoil@yahoo.com	

Compliance Summary:QtrQtr: NWNW Sec: 5 Twp: 2S Range: 56W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
06/19/2012	667500024			V			Y
10/06/2010	200280177	ES	PR	U			Y
06/24/2010	200257742	ES	AC	U			Y
06/10/2010	200255403	ES	AC	U			Y
03/02/2010	200237325	SR	PR	U			Y
10/14/2009	200220615	ES	PR	U			Y
05/27/2009	200212937	ES	PR	U			Y
08/22/2008	200196557	PR	SI	U			Y
03/23/2001	200015353	ES	PR	U	I	F	Y
03/19/2001	200015356	ES	PR	U		F	Y
08/25/2000	200009410	PR	PR	S		P	N
07/07/1999	872980	ID	SI			F	Y
06/30/1997	500158610	PR	PR			P	N
11/07/1995	500158609	PR	PR			F	
11/06/1995	500158608	PR	PR			P	N
09/28/1995	500158607	PR	PR			F	Y
09/26/1995	500158606	PR	PR			F	Y
09/18/1995	500158605	PR	PR			F	Y
06/19/1995	500158604	PR	PR			P	N

Inspector Comment:

Inspector Name: AXELSON, JOHN

Follow up inspection to document corrective actions required by NOAV #200353921 and Remediation Project #5051. Spill observed on 5/8/12 has been cleaned up. However, no Form 19 was ever submitted to document spill and no information regarding confirmation soil samples or waste disposal was submitted. An ongoing release or new release was observed at the east side of the plant building where a pipe enters the structure. Same condition was observed on 5/8/12. Remediation of oily waste Proj #5051 is ongoing on south side of plant - area has recently been tilled. The following corrective actions are still required: 1) Secondary containment berms need maintenance. 2) Some junk & trash accumulating on location again needs to be cleaned up. 3) Still need to submit Form 19 to document previous spill. 4) Stop release on east side of plant building and make repairs. 5) Provide confirmation sample results and waste disposal documentation for spill observed on 5/8/12. 6) Continue to treat oily waste per Proj #5051 in accordance with 907.e. and provide annual update report for Proj #5051 with sample results no later than 10/31/13. Corrective actions 1-5 required no later than 2/28/13.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
234106	WELL	PA	01/29/1953		121-06205	KEJR 2	
234109	WELL	SI	06/05/2012	OW	121-06208	LITTLE BEAVER UNIT 44	

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number: (S/U/V) _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TRASH	Unsatisfactory	Some junk & trash - plastic, concrete, pipes, fittings, 5-gal containers.	Cleanup all junk & trash & properly dispose or recycle.	02/28/2013

Spills:

Type	Area	Volume	Corrective action	CA Date
Produced Water		<= 5 bbls	Ongoing release or new release at pipe entering the east side of building. Immediately prevent additional release and make repairs.	02/28/2013

☐ Multiple Spills and Releases?

Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
S/U/V:			Comment:		
Corrective Action:				Corrective Date:	
<u>Paint</u> Condition <input style="width: 150px;" type="text"/> Other (Content) _____ Other (Capacity) _____ Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth		Walls Insufficient	Base Insufficient	Inadequate	
Corrective Action	Maintain berms during routine maintenance.			Corrective Date	02/19/2013
Comment					
<u>Venting:</u>					
Yes/No	Comment				
<u>Flaring:</u>					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	

Predrill

Location ID: 316986

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____**Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____**Date:** _____**Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Environmental****Spills/Releases:**

Type of Spill: OIL Description: and water Estimated Spill Volume: _____

Comment: Spill on north side of injection plant observed on 5/8/12 appears to have been cleaned up. A Form 19 to document the release was never submitted. The Form 19, confirmation soil samples to verify compliance with Table 910-1 and waste disposal documentation are still required.

Corrective Action: See comment

Date: 02/28/2013

Inspector Name: AXELSON, JOHN

Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____	

Water Well:

	Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____

Field Parameters:

Sample Location: _____

Waste Management:

Type	Management	Condition	Comment	GPS (Lat)	(Long)
Oily Soil	Land Treatment	Adequate	Continue to routinely till oily waste in landfarm area on south side of plant per Rem #5051. Add microbes, nutrients, moisture as needed. Submit annual report with sample results by 10/31/13.		

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Inspector Name: AXELSON, JOHN

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
667500097	Ongoing release at piping on east side of plant	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3039298
667500098	housekeeping	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3039299
667500099	berms & trash	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3039300
667500100	land treatment area for Rem #5051	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3039301