



State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax: (303) 894-2109



FOR OGCC USE ONLY

RECEIVED  
1/11/2013

ACCIDENT REPORT

As required by Rule 602.b.

Report taken by:

DESCRIPTION OF ACCIDENT (Please be as specific as possible)

Name of Operator: Encana Oil and Gas
Date of Incident: 1/7/2012
Type of Facility (well, tank battery, flow line, pit): Access road/area at top of Douglas Pass
Well Name & Number: access road
API Number: 05103099410000
Connect to Accident (land owner, royalty owner, etc.) Encana

Location	
County: Garfield	
Field Name: Rangley	
QtrQtr: SENE	Section: 26
Township: 5S	Range: 102 W
Meridian: 4	

Provide a detailed description of the accident, problem, and cause (equipment failure, human error, etc.):

On 1/7/2013 at approximately 9:30 a.m. two employees were riding snow machines at the top of Douglas Pass to access gas wells in that area. One of the employees was mounting his snow machine and in doing so, twisted his knee and felt it "pop". He says he instantly felt extreme pain. The second employee was able to help the first employee get to vehicle where he was then transported to hospital for medical attention. The initial medical exam was reported that the right knee had been dislocated.

Other Notifications

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact Person	Response

Accident Tracking No: \_\_\_\_\_