

COGCC Field Inspection Report

Doc # 663801244

RE: SKR 598-35AV-18 API 05-045-14393

Finding: 200 psi on braden.

Corrective Action complete 07/26/2013

Braden pressure for this well was bleed to 0