

FORM
6Rev
12/05

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

400479338

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10254

Contact Name: Rich Larson

Name of Operator: RED MESA HOLDINGS/O&G LLC

Phone: (970) 588-3302

Address: 5619 DTC PARKWAY - STE 800

Fax: (970) 588-3562

City: GREENWOOD State: CO Zip: 80111

Email: rlaron@redmesa1.com

For "Intent" 24 hour notice required,

Name: LABOWSKIE, STEVE

Tel: (970) 946-5073

COGCC contact:

Email: steve.labowskie@state.co.us

API Number 05-067-06230-00

Well Name: DYE-HARD

Well Number: 3

Location: QtrQtr: NENW Section: 13 Township: 33N Range: 12W Meridian: N

County: LA PLATA

Federal, Indian or State Lease Number: 25082

Field Name: RED MESA

Field Number: 72890

☒ Notice of Intent to Abandon☐ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 37.109750

Longitude: -108.104030

GPS Data:

Date of Measurement: 10/07/2008

PDOP Reading: 1.9

GPS Instrument Operator's Name: SAM PETERSEN

Reason for Abandonment:

☐ Dry☒ Production for Sub-economic☐ Mechanical Problems☐ OtherCasing to be pulled: ☐ Yes☒ No

Estimated Depth: 3646

Fish in Hole: ☐ Yes☒ No

If yes, explain details below

Wellbore has Uncemented Casing leaks:

☐ Yes☒ No

If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Code	Perf. Top	Perf. Bottom	Date	Method of Isolation	Plug Depth
DAKOTA	DKTA	3500	3638	01/01/2008	CEMENT	3646

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
CONDUCTOR	12+1/4	9+5/8	40	84	6	84	0	VISU
1ST	6+1/4	4+1/2	10.5	3,646	60	3,646	2,900	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 3646 with 19 sacks cmt on top. CIPB #2: Depth 2710 with 30 sacks cmt on top.
CIBP #3: Depth 1085 with 30 sacks cmt on top. CIPB #4: Depth 586 with 30 sacks cmt on top.
CIBP #5: Depth 134 with 45 sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set <u>19</u> sks cmt from <u>3646</u> ft. to <u>3451</u> ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input checked="" type="checkbox"/>
Set <u>30</u> sks cmt from <u>2710</u> ft. to <u>3610</u> ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input checked="" type="checkbox"/>
Set <u>30</u> sks cmt from <u>1085</u> ft. to <u>985</u> ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input checked="" type="checkbox"/>
Set <u>30</u> sks cmt from <u>586</u> ft. to <u>486</u> ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input checked="" type="checkbox"/>
Set <u>45</u> sks cmt from <u>134</u> ft. to <u>0</u> ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input checked="" type="checkbox"/>

Perforate and squeeze at 2660 ft. with 18 sacks. Leave at least 100 ft. in casing CICR Depth

Perforate and squeeze at 1035 ft. with 18 sacks. Leave at least 100 ft. in casing CICR Depth

Perforate and squeeze at 536 ft. with 18 sacks. Leave at least 100 ft. in casing CICR Depth

(Cast Iron Cement Retainer Depth)

Set 22 sacks half in. half out surface casing from 134 ft. to 0 ft. Plug Tagged: ☐

Set 23 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☒ Yes ☐ No

Set 0 sacks in rat hole Set 0 sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: ft. of inch casing Plugging Date:

*Wireline Contractor: *Cementing Contractor:

Type of Cement and Additives Used:

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No *ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: Print Name: Monty Collins

Title: Consultant Date: Email: patch1094@yahoo.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Date:

CONDITIONS OF APPROVAL, IF ANY: Expiration Date:

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

400479437	PROPOSED PLUGGING PROCEDURE
400479448	WELLBORE DIAGRAM
400479454	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

User Group

Comment

Comment Date

--	--	--

Total: 0 comment(s)