

FORM
22
Rev 5/99

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax: (303) 894-2109



FOR OGCC USE ONLY

ACCIDENT REPORT

As required by Rule 602.b.

Report taken by:

DESCRIPTION OF ACCIDENT (Please be as specific as possible)

Name of Operator: Encana Oil and Gas
Date of Incident: 3/31/2014
Type of Facility (well, tank battery, flow line, pit): Well
Well Name & Number: Douglas Creek 54
API Number: 05-103-09523-0000
Connect to Accident (land owner, royalty owner, etc.) Contractor

Location	
County: Rio Blanco	
Field Name: Douglas Creek	
QtrQtr: NWSE	Section: 2
Township: 3S	Range: 102W
Meridian: 6th Principal	

Provide a detailed description of the accident, problem, and cause (equipment failure, human error, etc.):

A roustabout crew was working on the Douglas Creek 54. On that location there has been some settling soil around the well head that has caused the flow line coming off of the well head to come under stress. This issue was entered into IMS as Hazard ID H2014-00554. The roustabouts were taking the equipment apart so it could be replaced. Just as the rail road union came free the pipe under stress jolted, causing the 36" pipe wrench the roustabout was using to hit him in the face. Causing a slight chip in his left incisor. The other members of the crew inspected his tooth. They noted no bleeding and no other damage. So the crew and the contractor in question decided to continue working.

Other Notifications

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact Person	Response

Accident Tracking #: I2014-00314 ___