

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

04/16/2014

Document Number:

673702393

Overall Inspection:

**ACTION REQUIRED****FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	209601	322184	Sherman, Susan	<input type="checkbox"/>	

**Operator Information:**

OGCC Operator Number: 10170

Name of Operator: CRIMSON EXPLORATION OPERATING INC

Address: 717 TEXAS AVENUE SUITE 2900

City: HOUSTON State: TX Zip: 77002

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Williams, Roy	(713) 898-2637	rwilliams@crimsonxp.com	
LaFevers, Jim	(713) 898-2637	jlafevers@crimsonxp.com	

**Compliance Summary:**

QtrQtr: NESE Sec: 19 Twp: 6S Range: 64W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/23/2012	668200251	PR	PR	SATISFACTOR Y	P		No
08/07/2012	668200076	PR	PR	SATISFACTOR Y	I		No
11/09/2010	200284138	PR	PR	SATISFACTOR Y			No
06/30/2010	200261327	PR	SI	ACTION REQUIRED			Yes
09/17/2007	200124278	PR	PR	ACTION REQUIRED			Yes
07/04/2002	200028387	PR	PR	ACTION REQUIRED		Fail	Yes
05/14/1999	500141550	PR	PR			Fail	Yes
10/10/1996	500141549	PR	PR			Fail	Yes

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
115104	PIT		09/23/1999		-	EVERITT 43-19	<input type="checkbox"/>
209601	WELL	PR	08/09/1985	OW	039-06506	RMPCO-EVERITT-UPRR 43-19	PR <input checked="" type="checkbox"/>

**Equipment:****Location Inventory**

Inspector Name: Sherman, Susan

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

### Location

#### Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	ACTION REQUIRED	Rutted.	Maintain.	06/30/2014

#### Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
CONTAINERS	SATISFACTORY			
OTHER	SATISFACTORY	lease sign at 174		
BATTERY	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number: (S/U/V) \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

#### Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

#### Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
PUMP JACK	SATISFACTORY	steel panels		
TANK BATTERY	SATISFACTORY	barbed wire		
WELLHEAD	SATISFACTORY	barbed wire		

#### Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Deadman # & Marked	4	SATISFACTORY			
Prime Mover	1	SATISFACTORY	gas		
Bird Protectors	1	SATISFACTORY			
Ancillary equipment	2	SATISFACTORY	gas scrubber		
Gas Meter Run	1	SATISFACTORY	Solar		
Vertical Separator	1	SATISFACTORY	5 BBLs. Same berms as VHT.		

Inspector Name: Sherman, Susan

Veritcal Heater Treater	1	SATISFACTORY	40 BBLs. Berms 39.51145, - 104.58894		
Pump Jack	1	SATISFACTORY			

**Facilities:** ☐ New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST	,

S/A/V:		Comment:	same berms as crude oil tanks
Corrective Action:		Corrective Date:	

Paint

Condition	
-----------	--

Other (Content) \_\_\_\_\_

Other (Capacity) 140 BBLs \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action		Corrective Date	
Comment			

**Facilities:** ☐ New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST	39.511340,-104.588810

S/A/V:	SATISFACTORY	Comment:	
Corrective Action:		Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate

Corrective Action		Corrective Date	
Comment			

The subreport 'rptInsp8' could not be found at the

<b>Flaring:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 209601

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 209601 Type: WELL API Number: 039-06506 Status: PR Insp. Status: PR

**Producing Well**

Comment: Dec 2013 last reported production data.

The subreport 'rptInsp12' could not be found at the

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: Sherman, Susan

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

#### RESTORATION AND REVEGETATION

##### Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

##### Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

#### **Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: Sherman, Susan

Corrective Action:  Date

Overall Final Reclamation ☐

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail	Compaction	Fail	MHSP	Pass	
Gravel	Pass	Gravel	Pass			

S/U/V: **ACTION REQUIRED** Corrective Date: **06/30/2014**

Comment: **See photo for battery erosion. Surface indication of pit (see attached photo).**

CA: **Install stormwater BMPs to stop erosion and prevent offsite sediment transport.**

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<b>Submit plan to COGCC field inspector on schedule and implementation of access road and locations BMP installations where necessary for the locations in the area with erosion.</b>	ShermaSe	04/21/2014

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673702524	Crimson Everitt 43-19 well	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3325409">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3325409</a>
673702525	Crimson Everitt 43-19 well	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3325410">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3325410</a>
673702526	Crimson Everitt 43-19 well	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3325411">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3325411</a>
673702527	Crimson Everitt 43-19 Bat	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3325412">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3325412</a>
673702528	Crimson Everitt 43-19 Bat	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3325413">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3325413</a>
673702529	Crimson Everitt 43-19 Bat	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3325414">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3325414</a>
673702530	Crimson Everitt 43-19 Bat	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3325415">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3325415</a>
673702531	Crimson Everitt 43-19 Bat	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3325416">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3325416</a>
673702532	Crimson Everitt 43-19 Bat	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3325417">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3325417</a>