

VEGA UNIT-610S93W9NWNE

Scroll down to view all pictures



Staining from leaking around valve stem.



Leaking around valve stem