

KNAUS 66S93W 19SWSW

Inspection DOC# 675200187

Trash on location



Some erosion and  
rilling on cut slope.



Unmarked conductor

