

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
06/24/2014

Document Number:
674900032

Overall Inspection:

ACTION REQUIRED

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>214498</u>	<u>325293</u>	<u>Hughes, Jim</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>96735</u>
Name of Operator:	<u>WILLIFORD RESOURCES, L.L.C.</u>
Address:	<u>6506 S LEWIS AVE STE 102</u>
City:	<u>TULSA</u> State: <u>OK</u> Zip: <u>74136</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Maclaren, Joe		joe.maclaren@state.co.us	
FISCHER, ALEX		alex.fischer@state.co.us	
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	
Roy, Catherine		catherine.roy@state.co.us	
LABOWSKIE, STEVE		steve.labowskie@state.co.us	
Callahan, Linda	(918) 712-8828	lcallahan3@swbell.net	e-mail recipient

Compliance Summary:

QtrQtr:	<u>NENW</u>	Sec:	<u>7</u>	Twp:	<u>33N</u>	Range:	<u>11W</u>
---------	-------------	------	----------	------	------------	--------	------------

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/17/2013	663401284	PR	PR	VIOLATION	F		Yes
05/30/2013	669400712	PR	PR	VIOLATION	F		Yes
05/07/2013	669400644	PR	PR	VIOLATION	I		Yes
07/08/1997	500147436	ID	SI			Pass	No
08/26/1996	500147435	ID	SI			Pass	No
10/18/1995	500147434	ID	TA				Yes

Inspector Comment:

On June 24, 2014 COGCC staff members Alex Fischer, Jim Hughes, Joe Maclaren, and Catherine Roy conducted a joint field inspection of the Williford Resources L and S #6. Please refer to document #663401284 for the most recent inspection report. An unlined open pit #118933 was observed on the northwest side of the location. This pit contains what appear to be drill cuttings. The pit is overgrown with vegetation. An approximately 2' by 10' area of stained soils was noted in the south corner of the pit. A Form 27 site investigation and remediation work plan shall be submitted to COGCC EPS staff regarding closure of this pit in accordance with the 900 and 1000 series rules. An approximately 20' diameter area of stained soil was observed southwest of the pump jack. As noted on prior inspections, the stuffing box leaks and there is free product on and around the wellhead. The northern edge of the location is eroding due to storm water run off.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
118933	PIT		09/23/1999		-	LONG & SCHLUTER 6	<input checked="" type="checkbox"/>
214498	WELL	PR	01/01/2011	OW	067-06101	LONG & SCHLUTER 6	PR <input checked="" type="checkbox"/>

Equipment:		Location Inventory	
Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Action Required	comment	Corrective Action	Date
Main	SATISFACTORY			

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V): ACTION Corrective Date: 08/04/2014

Comment: Emergency contact number listed as 911.

Corrective Action: A local emergency contact number needs to be listed on wellhead sign.

Spills:				
Type	Area	Volume	Corrective action	CA Date
Other		<= 5 bbls	Approximately 20' diameter area of stained soil west of pump jack. Remove stained soil and dispose of properly.	08/04/2014
Other		<= 5 bbls	2' by 10' area of stained soil on southern edge of open pit. Remove stained soil and dispose of properly.	08/04/2014
Crude Oil	WELLHEAD	<= 5 bbls	Fix stuffing box leak.	08/04/2014

Multiple Spills and Releases?

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
PUMP JACK	SATISFACTORY			

Equipment:					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Pump Jack		ACTION REQUIRED	Lube oil leak underneath motor.	Fix leak. Remove oil stained soil and dispose of properly.	08/04/2014

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 214498

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 118933 Type: PIT API Number: - Status: _____ Insp. Status: _____

Facility ID: 214498 Type: WELL API Number: 067-06101 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? **Fail** CM **Open pit #118933**

CA **Submit Form 27 to EPS staff for pit closure.** CA Date **08/04/2014**

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? **Fail** Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Inspector Name: Hughes, Jim

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ F _____

Comment: _____

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: **ACTION REQUIRED** Corrective Date: **08/22/2014**

Comment: **Nothern edge of location has erosion due to stormwater run off.**

CA: **Stabilize the northern edge of location to prevent further erosion from stormwater.**

Pits: NO SURFACE INDICATION OF PIT

Inspector Name: Hughes, Jim

Pit Type: Drilling Pit Lined: NO Pit ID: 118933 Lat: 37.124077 Long: -108.085624

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Pit (S/AV): ACTION Comment: Submit a Form 27 to COGCC EPS staff for pit closure.

Corrective Action: Close pit in accordance with 900 and 1000 series rules. Date: 08/04/2014

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674900033	Stuffing Box Leak	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3390794
674900034	Stained Soil	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3390795
674900035	Pit #118933	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3390796
674900036	Lube Oil Leak	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3390797