



1.) Location entrance. Undercutting and sediment runoff observed.



2.) Location stockpile being tracked. Slash utilized as BMP but contains a lot of topsoil without additional runoff BMPs.



3.) Fill untracked/ vulnerable to erosion.





4.) Primary perimeter berm being constructed.