

## Lewis USA 36-1

Inspection DOC# 675200368

Sediment and debris on  
location from flood.  
Containment is at  
capacity.



No containment around  
produced water tank.





Damaged riser. Venting  
at time of inspection.



Damaged gathering line.





Exposed pipeline in  
roadway. (exposed in  
multiple location along  
road)



Exposed pipeline in  
roadway.

