

Federal 31-3

Inspection DOC# 675200380

Location entrance is
blocked by pile of
material. Location is
being accessed by ATV.



Sediment run-on from
recent flooding.



Location shot.

