

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

Inspection Date:

09/10/2014

Document Number:

668302379

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 203296 | 320268 | JOHNSON, RANDELL | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 27635Name of Operator: ENERGY SEARCH COMPANYAddress: 12101 EAST 2ND AVENUE #100City: AURORA State: CO Zip: 80011

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|----------------------|---------|
| Marisco, Joe | | joemarisco@yahoo.com | |
| Roebuck, Don | | don_roebuck@msn.com | |

Compliance Summary:QtrQtr: SWNW Sec: 18 Twp: 1S Range: 67W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 12/18/2013 | 668701301 | PR | PR | ACTION REQUIRED | F | | No |
| 07/20/2010 | 200275857 | PR | PR | ACTION REQUIRED | | | Yes |
| 01/02/2008 | 200128714 | PR | PR | ACTION REQUIRED | | | Yes |
| 01/13/2000 | 895070 | PR | PR | SATISFACTORY | | Pass | No |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 203296 | WELL | PR | 03/31/2008 | OW | 001-08805 | GREEN 3 | UN | <input checked="" type="checkbox"/> |
| 413081 | WELL | PR | 05/05/2014 | GW | 001-09709 | CARLSON 12-18 | PR | <input type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Lease Road: | | | | |
|--------------------|------------------------------|--|--------------------------|------------|
| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
| Access | ACTION REQUIRED | Lease access road is eroded and rutted | Repair lease access road | 10/10/2014 |

| Signs/Marker: | | | | |
|----------------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD | SATISFACTORY | | | |

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

| Spills: | | | | |
|----------------|-----------|-----------|---|------------|
| Type | Area | Volume | Corrective action | CA Date |
| Other | | <= 5 bbls | Remove or remediate stained soil around pumpjack motor/See attached photos on last page of document | 10/10/2014 |
| PW/CO | WELLHEAD | <= 5 bbls | Remove or remediate stained soil around wellhead/See attached photos on last page of document | 10/10/2014 |
| Other | Pump Jack | <= 5 bbls | Remove or remediate stained soil around pumpjack/See attached photos on last page of document | 10/10/2014 |

☒ Multiple Spills and Releases?

| Fencing/: | | | | |
|------------------|------------------------------|--------------------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| PUMP JACK | SATISFACTORY | Angle-iron fencing | | |

| Equipment: | | | | | |
|-------------------|---|------------------------------|---|--------------------------|------------|
| Type | # | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| Prime Mover | 1 | ACTION REQUIRED | Gas engine - Engine is leaking contaminating fluids onto the ground | Repair leaks on engine | 10/10/2014 |
| Pump Jack | 1 | ACTION REQUIRED | Pumpjack is leaking contaminating fluids onto the surrounding soil | Repair leaks on pumpjack | 10/10/2014 |

| | | | | | |
|--------------------|------------------------------|-----------------------------------|---------------------|---|------------------|
| Facilities: | | <input type="checkbox"/> New Tank | | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS | |
| | | | CENTRALIZED BATTERY | 39.971550,-104.935420 | |
| S/A/V: | SATISFACTORY | | Comment: | See related inspection document #668302368 for information concerning shared facilities and equipment | |
| Corrective Action: | | | | | Corrective Date: |
| Paint | | | | | |
| Condition | Adequate | | | | |
| Other (Content) | _____ | | | | |
| Other (Capacity) | _____ | | | | |
| Other (Type) | _____ | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Corrective Action | | | | | Corrective Date |
| Comment | | | | | |
| Venting: | | | | | |
| Yes/No | Comment | | | | |
| NO | | | | | |
| Flaring: | | | | | |
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date | |
| | | | | | |

Predrill

Location ID: 203296

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 203296 Type: WELL API Number: 001-08805 Status: PR Insp. Status: UN

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

S/A/V: _____ CA Date: _____

CA: _____

Comment: No production records on file with COGCC since March 2013

BradenHead

Comment: Bradenhead is not plumbed to the surface

CA: Bradenhead must be plumbed to the surface to facilitate inspection access

CA Date: 10/10/2014

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): N _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): YES _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? Pass CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? In _____ Production areas stabilized ? Pass _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In
 Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|------------|
| Compaction | Pass | Compaction | Fail | | | |
| Gravel | Pass | Gravel | Fail | | | |
| Other | Pass | Other | Fail | | | Vegetation |

S/A/V: **ACTION REQUIRED** Corrective Date: **10/10/2014**

Comment: **Erosion and rutting along lease access road**

CA: **Repair lease access road**

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 668302380 | Energy Search - Green 3 (001-08805) (1) | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3429725 |
| 668302381 | Energy Search - Green 3 (001-08805) (2) | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3429726 |
| 668302382 | Energy Search - Green 3 (001-08805) (3) | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3429727 |
| 668302383 | Energy Search - Green 3 (001-08805) (4) | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3429728 |
| 668302384 | Energy Search - Green 3 (001-08805) (5) | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3429729 |
| 668302385 | Energy Search - Green 3 (001-08805) (6) | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3429730 |
| 668302386 | Energy Search - Green 3 (001-08805) (7) | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3429731 |
| 668302387 | Energy Search - Green 3 (001-08805) (8) | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3429732 |
| 668302388 | Energy Search - Green 3 (001-08805) (9) | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3429733 |
| 668302389 | Energy Search - Green 3 (001-08805) (10) | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3429734 |
| 668302390 | Energy Search - Green 3 (001-08805) (11) | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3429735 |

ACTION REQUIRED

ANY ACTION REQUIRED items listed on this report indicate that the oil and gas facility or the oil and gas operations listed on the report may be in violation of the rules and regulations of the Colorado Oil and Conservation Commission (“COGCC”) and corrective action is required.

There is reasonable cause to believe that a violation of the Oil and Gas Conservation Act, or of any rule, regulation, or order of the Commission, or of any permit issued by the Commission, has occurred. The Operator’s compliance with this Inspection Report is required to resolve these alleged violations. This document requires the Operator to timely respond to the COGCC and to comply with directives as listed by the **Corrective Action Deadline Date**. Failure to do so will result in the issuance of a Notice of Alleged Violation and initiation of enforcement proceedings in which COGCC will seek monetary penalties for the alleged violations pursuant to § 34-60-121, C.R.S. and Rule 523, COGCC Rules of Practice and Procedure, 2 CCR 404-1. (Please note that the COGCC's penalty authority was recently increased to a maximum of \$15,000 per day and penalties are no longer capped at a maximum of \$10,000 per violation.)